

ASS. REC. BY: Steve

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 (OD / TP / WS / TP RES / OD RES / EVA / INV / LMV)
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. 1800014507
 Claims No. 7516049729SG
 Sum Insured: _____ Excess: 300
 (Client's Record)
 Make of Veh: _____

Veh No: SFZ 7767S Yr Regn: 12/2/18
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
 Make: Mitsubishi Guttanjer c.c. 1998
 Colour: White A/C: Insured / Std / NI / N
 Sp. Reading: 115535 T/Radio: Insured / Std / NI / N
 Eng/No: _____
 C/No: GF7W9491179
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/R/m / STD A/R/m or
 Tyre Size: F: 225/55R18
 R: 11

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/> N/S	<input checked="" type="checkbox"/> O/S
<input type="checkbox"/>	<input type="checkbox"/>

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or TYG

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 C/A / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 7 days Res.: Yes or No
 Cum Sum: _____ % 3 Val.: Yes or No

Front Rear
 R/Bal. 4 mm R/Bal. 4 mm
 L/Bal. 4 mm L/Bal. 4 mm
 D.O.A. 5/2/21 O.O.I. 8/2/21
 Survey held at Cycle & Carriage

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<i>The new</i> Part remark - Aero Kit was broken - Part take from SLX 7631P.
	<u>MV-89K</u>
09/02/21 @ 9.36am	revert to AIG via Merimen.
10/02/21 @ 11.58am	Kok Chong informed C/A via Merimen.
10/02/21 @ 12.13pm	Informed Don C/A & ex \$300 by email.
19/04/21 @ 4.09pm	confirmed with Ms Loi final fig \$6060.99, 7 days (Red \$4744, 44%)

Prell. Report
 Final Report

Days Of Repair: 7

Resurvey No. of Trip: 2

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Inve (\$)
 : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS \$


Photos

Others

TOTAL

MER-OD

6060.99



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X


Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/Abdul Jalil Bin Mohamad
	Reg No/Reg Date	SFZ7767S / 12/02/201
	Date In/Mileage	/ 0
	Chassis No	GF7W0401119
	Engine No	4J11XK6012
	Make/Model	MIT/OUTLANDER 2.0 2WD CVT SPORTS (9
	Colour/Trim	W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	08/02/2021/ 09:49	QUD	247 / DonBong	62784			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2700.00
RENEW ACCIDENT DAMAGED PARTS ON LH REAR DOOR, CUT/WELD LH SIDE SILL PANEL, REPAIR LH FRONT DOOR, REPAIR LH REAR FENDER, REPAIR REAR BUMPER FACE					2 1/2 X 450			1125
E PNT88000								120.00
TRANSFER LH REAR DOOR TRIM, DOOR GLASS, MECHANISM AND OTHERS ATTACHMENT TO NEW DOOR PANEL								
E PNT88000								120.00
REMOVE AND INSTALL FLOOR CARPET AND SIDE TRIM CABIN TO FACILITATE REPAIR WORK (photo)								
E PNT98000								2100.00
PAINT WORK SPRAY LH FRONT DOOR, LH REAR DOOR, LH SIDE SILL PANEL, LH REAR FENDER, REAR BUMPER AND AFFECTED PORTION					5 X 350			1750
E PNT88000								80.00
REMOVE AND INSTALL AERO KIT								
M SUNDRY								40 80.00
APPLY BODY SEALANT								
A 54900099								30.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								
M SUNDRY								40 80.00
PERFORM RUST PREVENTION								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								
A WHEELALIGNMENTBP								120.00
To Conduct Computerize Full Wheel Alignment								
M SUNDRY								30.00
LABOUR RENEW LH REAR SPORT RIM INCLUDING BALANCING								
M SUNDRY								320.00
RE-APPLY ZERTONA COATING (provide sales agreement)								
M SUNDRY								20 50.00
SUNDRIES								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Abdul Jali Bin Mohamad Reg No/Reg Date SFZ7767S / 12/02/201 Date In/Mileage / 0 Chassis No GF7W0401119 Engine No 4J11XK6012 Make/Model MIT/OUTLANDER 2.0 2WD CVT SPORTS (9 Colour/Trim W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Qty	Unit Price	Disc%	Amount
KAX00008	Credit	08/02/2021/ 09:49	QUD	247 / DonBong	62784				
Description of Goods / Services						Qty	Unit Price	Disc%	Amount
M	SIDE SILL,FR FLOOR,OTR LH	DD				1.00	802.00	23.00	617.54
M	PANEL ASSY,RR DOOR,LH	DD				1.00	937.00	23.00	721.49
M	W/STRIP,RR DOOR OPNG,FR LH	DD				1.00	129.00	23.00	99.33
M	W/STRIP,R/DR OPN,LWR OTR L	DD				1.00	33.00	23.00	25.41
M	TAPE,RR DOOR SASH	npc				1.00	42.00	23.00	32.34
M	TAPE,RR DOOR SASH	npc				1.00	42.00	23.00	32.34
M	GARNISH,FR DOOR,LH	CUT				1.00	190.00	23.00	146.30
M	GARNISH,RR DOOR,LH	CUT				1.00	164.00	23.00	126.28
M	AIR DAM,SIDE,LH	X				1.00	541.00	23.00	416.57
M	AERO KIT - OUTLANDER	X CUT (Salvage from SLX 7631P.)				1.00	1554.00	00.00	1554.00
M	WHEEL,SPARE TIRE DISC	CUT				1.00	1102.00	23.00	848.54
M	MOULDING,RR WHEEL ARCH,LH	CUT				1.00	199.00	23.00	153.23
M	MOULDING,RR BUMPER,LH	CUT				1.00	106.00	23.00	81.62

Estimate

SURVEYOR NAME : Steve CLKK) 8/2/21, 3.00pm
 SURVEYOR SIGNATURE : DD-NM AL
 DATE : Excess - ?
 REMARKS : P/P
 Ry Bel...
 7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Confirm & accepted by

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Authorized signatory and company stamp

Nett	10,804.99
7% GST on	10804.99
Total Payable	11,561.34

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available discreetly.

ACCIDENT STATEMENT

Date of Submission 08/02/2021 12:14 (SGT)
Date of Accident 05/02/2021 21:50 (SGT)
Exact Location of Accident Pasir Ris, Singapore
Additional Location Information PASIR RIS DRIVE 8 JUNCTION PASIR RIS DRIVE 1
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SFZ7767S

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner ABDUL JALIL BIN MOHAMAD
NRIC No SXXXX325J
Email Address ABDULJALILMOHAMAD@HOTMAIL.COM
Mobile Phone No (Phone) +65-97645914
Alternative Phone No (Home) +65-97645914

VEHICLE PARTICULARS

Manufacturer Mitsubishi
Model Outlander
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private car

INSURANCE COMPANY

Name of Insurance Company AIG
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 1800014507-01
Cover Note Number -

DRIVER

Name of Driver ABDUL JALIL BIN MOHAMAD
NRIC No SXXXX325J
Date Of Birth 24/04/1965
Occupation Indoor

Date Of Driving Pass
 Driving experience
 Gender
 Mobile Number
 Alt. Phone Number
 Email Address
 Address
 Address complement
 Postcode
 Is the driver the policyholder?
 If No, Relationship of the Driver with the Insured
 Does Driver Own Other Vehicles?
 Vehicle Registration Number of Other Vehicle Owned by Driver
 Insurance Company of Other Vehicle Owned by Driver

23/05/1992
 28 YEARS AND 9 MONTHS
 Male
 (Phone) +65-97645914
 (Home) +65-97645914
 ABDULJALILMOHAMAD@HOTMAIL.COM
 BLK 129 PASIR RIS STREET 11 \$02-327
 -
 510129
 Yes
 -
 No
 -
 -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
 Weather Conditions
 Road Surface

Collision - Change/cross lane
 Clear
 Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
 Number of vehicles involved in the accident
 Was anybody injured in the Accident?
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged?
 Number of Passengers (Including Driver)
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

No
 2
 No
 -
 Yes
 2
 No

PASSENGER 1

Name
 Gender

ZAHRAH MOHAMAD
 Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?
 Was notice of intended Prosecution given?
 If yes, against whom?

No
 No
 -

CIRCUMSTANCES OF ACCIDENT

REFER ATTACHMENTS.

ATTACHMENT(S)

Are accident photos available for attachment?
 Was there any video captured by Car Camera?
 Was there any audio recorded?

Yes
 Yes
 No

DETAILS OF OTHER VEHICLE PROPERTY:

Vehicle Registration Number
 Vehicle Manufacturer
 Vehicle Model
 Vehicle Variant
 Vehicle Colour
 Vehicle Category
 Name of Driver
 NRIC No

SMP4925S
 Honda
 Shuttle
 -
 White
 Private hire
 YEO CHEE BENG
 SXXXX939G

Contract Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Abdus 8/2/2021.

Policyholder's Signature / Date & Time	Driver's Signature (if driver is not the policyholder) / Date & Time	Witnessed by Reporting Centre Personnel
<p>Sketch Plan</p> <p>A : \$277675 B : SMP 49255</p>	<p style="text-align: center;">/ 7 /</p>	<p style="text-align: center;">↑ ↓</p> <p style="text-align: center;">PASIR RIS DR 1</p>

Describe Circumstances of the Accident

On 5th Feb 2021 at 2:50hrs, I was driving my vehicle SF277675 along Pasir Ris Ave 8 towards Junction of Pasir Ris Drive 1.

As I was travelling along the 2nd lane approaching the traffic junction, a motor car (SMP 49255) coming from the 3rd lane cut into the 2nd lane which is in front of me. As that 2nd lane is meant for going straight and turning right.

However, the said car did not make a right turn but stopped at the junction and he signal left indicator light which I perceived that he was not going to turn to the right but instead going straight.

So I decided to overtake him and switched my lane over ensuring that there was no oncoming vehicles coming from my rear right. However, as I was maneuvering my car to switch lane, my car accidentally side swipe the front car which resulted damages to both vehicles.

(Damages to vehicle as follows)

CAR A (SF2 77675)

- Rear Left door damage and scratches on the rim (rear left)

CAR B (SMP 49255)

- Damage to the rear right side bumper

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

8/2/2021
08:35 am

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

CERTIFICATE OF INSURANCE

CYCLE & CARRIAGE AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : ABDUL JALIL BIN MOHAMAD
Period of Insurance : 12 Feb 2020 To 11 Feb 2021
Engine No. : 4J11XK6012
Chassis No. : GF7W0401110

Vehicle No. : SFZ77675
Policy No. : 1800014507-01
Endorsement No. :
Issued Date : 13 Jan 2020

ABOUT THE COVER

Make/Model : MITSUBISHI Outlander 2.0 Elegance/Sports
Engine Capacity/Tonnage : 1,998.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2018
Insuring with COE/PARF : Yes

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorized Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

ABDUL JALIL BIN MOHAMAD - \$600 (Own Damage), \$600 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

- 1 Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684601
- 2 Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
- 3 Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 20 Lang Kee Rd Singapore 159094 64708688
- 4 Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 675733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

(We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504620216

C&CMICP2 - SAGLEE

239 ALEXANDRA ROAD

SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

This computer generated document does not require a signature.

AIGSGMOBILEAPP