

ASS. REC. BY:

Steve

REF:

A16

CS/AIG21001855/Eqd3

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. 1900017500

Claims No. 3440858182SG


Sum Insured: \_\_\_\_\_ Excess: 0/-

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Turn Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: \_\_\_\_\_

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: \_\_\_\_\_

Colour: \_\_\_\_\_

Sp. Reading: \_\_\_\_\_

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Tourador

Front

R/Bal. \_\_\_\_\_

L/Bal. \_\_\_\_\_

D.O.A. \_\_\_\_\_

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

MIV- 73K

09/02/21 @ 11.19am revert to AIG via Merimen

10/02/21 @ 12.06pm Kok Chong informed C/A via Merimen

10/02/21 @ 12.36pm Informed Edwin C/A &amp; ex: \$0/- by email

05/03/21 @ 3.42pm confirmed with Larry final fig \$6525.60, 7 days (Red \$6816.40, 51%)

Date/Time, File, Pass to?



: Prel. Report

05/03 Typist



: Final Report

Date/Time, File Return to?

Add Fee:



: Site Insp (\$ \_\_\_\_\_)



: Interview (\$ \_\_\_\_\_)



: Tech. Invs (%) \_\_\_\_\_



: Weekend (%) \_\_\_\_\_

Days Of Repair: 7

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Provice

Others


TOTAL

Date/Time, File, Pass to?

MER-OD

Date/Time, File, Pass to?

6525.60



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/TAY HEAN CHEOW (ZHENG XIANZHAO)
	Reg No/Reg Date	SMJ5395X / 11/03/201
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5027526
	Engine No	G4FGJH716076
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	08/02/2021/ 12:51	QUE	261 / Edwin Caina	28720			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount	
E PNT88000							2400.00	
RENEW RR BUMPER, BOOTLID & RR END PNL				400 X 2			800	
REPAIR / ALIGN RR FLR PNL, LHR FENDER & RHR FENDER								
E PNT98000							2100.00	
RESPRAY RR BUMPER, RR END PNL, BOOTLID, RR FLR PNL, LHR FENDER & RHR FENDER				350 X 2			700	
E PNT88000							120.00	
REMOVE & REFIT BOOTLID COMPONENT								
E PNT88000							120.00	
REMOVE & REFIT RR FLR BOARD, TRIM, CARPET TO FACILITATE REPAIR				(phb)				
A 54900099							30.00	
CHECK WIRING ELECTRICAL SYSTEM								
A 10028901							120.00	
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST							50.00	
M SUNDRY								
SUPPLY RR NUMBER PLATE WITH CASING							60.00	
E PNT88000							60.00	
REMOVE & REFIT REVERSE SENSOR							?	
M SUNDRY							220.00	
SUPPLY REVERSE SENSOR							?	
M SUNDRY							80.00	
APPLY ANTI CORROSION ON AFFECTED AREAS							40	
M SUNDRY							60.00	
SUPPLY BODY PNL SEALANT								
M SUNDRY							40.00	
SUPPLY C&C BADGE								
M SUNDRY							20.00	
Sundries								
M COVER-RR BUMPER					1.00	651.00	20.00	520.80
M COVER-RR BUMPER LWR					1.00	241.00	20.00	192.80
M COVER-RR BUMPER FOG LAMP, LH					1.00	19.00	20.00	15.20
M COVER-RR BUMPER FOG LAMP, RH					1.00	19.00	20.00	15.20

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**  
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	<table> <tr> <td>Cust No/Name</td><td>/TAY HEAN CHEOW (ZHENG XIANZHAO)</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMJ5395X / 11/03/201</td></tr> <tr> <td>Date In/Mileage</td><td>/ 0</td></tr> <tr> <td>Chassis No</td><td>KNAF3416MK5027526</td></tr> <tr> <td>Engine No</td><td>G4FGJH716076</td></tr> <tr> <td>Make/Model</td><td>KIA/CERATO 1.6 A EX G333</td></tr> <tr> <td>Colour/Trim</td><td>ABP AURORA BLACK / WK SATURN BLACK</td></tr> </table>	Cust No/Name	/TAY HEAN CHEOW (ZHENG XIANZHAO)	Reg No/Reg Date	SMJ5395X / 11/03/201	Date In/Mileage	/ 0	Chassis No	KNAF3416MK5027526	Engine No	G4FGJH716076	Make/Model	KIA/CERATO 1.6 A EX G333	Colour/Trim	ABP AURORA BLACK / WK SATURN BLACK
Cust No/Name	/TAY HEAN CHEOW (ZHENG XIANZHAO)														
Reg No/Reg Date	SMJ5395X / 11/03/201														
Date In/Mileage	/ 0														
Chassis No	KNAF3416MK5027526														
Engine No	G4FGJH716076														
Make/Model	KIA/CERATO 1.6 A EX G333														
Colour/Trim	ABP AURORA BLACK / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	08/02/2021/ 12:51	QUE	261 / Edwin Caina	28720			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	LAMP ASSY-SIDE T/SIGNAL,LH	?			1.00	181.00	20.00	144.80
M	LAMP ASSY-SIDE T/SIGNAL,RH	?			1.00	181.00	20.00	144.80
M	EXTN WIRING ASSY-BWS	?			1.00	207.00	20.00	165.60
M	BEAM-RR BUMPER	?			1.00	318.00	20.00	254.40
M	STAY-RR BUMPER LH	?			1.00	65.00	20.00	52.00
M	STAY-RR BUMPER RH	?			1.00	65.00	20.00	52.00
M	ANTENNA ASSY-SMARTKEY	?			1.00	46.00	20.00	36.80
M	BRACKET-RR BEAM UPR MTG,LH	?			1.00	9.00	20.00	7.20
M	BRACKET-RR BEAM UPR MTG,RH	?			1.00	9.00	20.00	7.20
M	BRACKET-RR BEAM LWR,CTR	?			1.00	6.00	20.00	4.80
M	BRACKET-RR BEAM LWR MTG	?			2.00	6.00	20.00	9.60
M	COVER-RR BUMPER UNDER,RH	?			1.00	33.00	20.00	26.40
M	BRACKET ASSY-RR BPR SIDE UPR,L	?			1.00	25.00	20.00	20.00
M	BRACKET-ASSY RR BPR SIDE UPR,R	?			1.00	31.00	20.00	24.80
M	COVER-RR BUMPER UNDER,LH	?			1.00	33.00	20.00	26.40
M	TRIM ASSY-RR TRANSVERSE	?			1.00	41.00	20.00	32.80
M	PANEL ASSY-BACK	?			1.00	324.00	20.00	259.20
M	PANEL ASSY-TRUNK LID	DO			1.00	1297.00	20.00	1037.60
M	HINGE ASSY-TRUNK LID,LH	?			1.00	97.00	20.00	77.60
M	HINGE ASSY-TRUNK LID,LH	?			1.00	97.00	20.00	77.60
M	W/STRIP-TRUNK LID OPNG	CRU			1.00	100.00	20.00	80.00
M	LATCH ASSY-TRUNK LID	CUT			1.00	112.00	20.00	89.60
M	STRIKER ASSY-TRUNK LID	X			1.00	40.00	20.00	32.00
M	LOGO ASSY-KIA SUB	MC			1.00	32.00	20.00	25.60
M	EMBLEM-CERATO	MC			1.00	28.00	20.00	22.40
M	LAMP ASSY-CENTER GARNISH	?			1.00	690.00	20.00	552.00
M	LAMP ASSY-REAR COMB INSIDE,LH	?			1.00	608.00	20.00	486.40
M	LAMP ASSY-REAR COMB INSIDE,RH	?			1.00	608.00	20.00	486.40
M	LAMP ASSY-REAR COMB OUTSIDE,LH	X			1.00	675.00	20.00	540.00
M	LAMP ASSY-REAR COMB OUTSIDE,RH	X			1.00	675.00	20.00	540.00

Estimate

6612 (1 PK)

Confirm &amp; accepted by

SURVEYOR NAME: Steve (CLKK)SURVEYOR SIGNATURE: 8/2/21, 1.00pmDATE: 00- Not A/LREMARKS: Express - ?

Authorized signatory and company stamp

Net 11,480.00  
 7% GST on 11480.00 803.60  
**Total Payable 12,283.60**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission ..... 08/02/2021 13:23 (SGT)  
Date of Accident ..... 06/02/2021 18:00 (SGT)  
Exact Location of Accident ..... AYE, Singapore  
Additional Location Information ..... AYE (BUONA VISTA) TOWARDS CITY  
Country/State of Loss ..... Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SMJ5395X

### INSURED/POLICYHOLDER

Is company? ..... No  
Name Of Registered Owner ..... TAY HEAN CHEOW  
NRIC No ..... SXXXX689E  
Email Address ..... EDM99@ROCKETMAIL.COM  
Mobile Phone No ..... (Phone) +65-90265260  
Alternative Phone No ..... +65-90265260

### VEHICLE PARTICULARS

Manufacturer ..... Kia  
Model ..... Cerato  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... -  
Are you claiming under your own insurance policy for repair to your vehicle? ..... Yes  
Vehicle Category ..... Private car

### INSURANCE COMPANY

Name of Insurance Company ..... AIG  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... No  
Policy Number ..... 1900017500  
Cover Note Number ..... -

### DRIVER

Name of Driver ..... TAY HEAN CHEOW  
NRIC No ..... SXXXX689E  
Date Of Birth ..... 22/04/1976  
Occupation ..... Indoor



Driving Pass  
Experience  
Mobile Number  
Phone Number  
Email Address  
Address  
Address complement  
Postcode  
Is the driver the policyholder?  
If No, Relationship of the Driver with the Insured  
Does Driver Own Other Vehicles?  
Vehicle Registration Number of Other Vehicle Owned by Driver  
Insurance Company of Other Vehicle Owned by Driver

23/01/1996  
25 YEARS AND 1 MONTH  
Male  
(Phone) +65-90265260  
+65-90265260  
EDM99@ROCKETMAIL.COM  
BLK 441B CLEMENTI AVENUE 3 #10-17

122441

Yes

No

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident  
Weather Conditions  
Road Surface

Collision - Head to Rear  
Clear  
Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?  
Number of vehicles involved in the accident  
Was anybody injured in the Accident?  
Was any injured conveyed to hospital by ambulance?  
Was any other material or property damaged?  
Number of Passengers (Including Driver)  
Has the driver been approached by unknown person(s)  
soliciting/offering accident claims assistance?

No  
2  
No  
-  
Yes  
2  
No

#### PASSENGER 1

Name  
Gender

CATHY ZHU  
Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?  
Was notice of intended Prosecution given?  
If yes, against whom?

No  
No  
-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO ATTACHMENT

#### ATTACHMENT(S)

Are accident photos available for attachment?  
Was there any video captured by Car Camera?  
Was there any audio recorded?

Yes  
Yes  
No

#### DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number  
Vehicle Manufacturer  
Vehicle Model  
Vehicle Variant  
Vehicle Colour  
Vehicle Category  
Name of Driver  
Contact Number

SKD5939H  
Volvo  
-  
Gray  
Private car  
MADELEINE ZHUO  
(Phone) +65-82685773

Business complement

Insurance code

Insurance Company Name

Nature Of Damage

Details of property damaged in accident

No. Of Passenger (Including Driver)

-  
-  
-  
Aviva  
-  
-  
-



## SKETCH PLAN

### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that :  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

### Sketch Plan



Describe Circumstances of the Accident

I was driving along AYE towards City direction. The vehicles in front of my car braked suddenly. I managed to brake in time but the car behind me was unable to and hit on the back of my car.


Declaration

We declare the foregoing particulars are true in every respect.

  
8/2/21 @ 9:55 hrs

Policyholder's Signature / Date &  
Time

Driver's Signature (If driver is not the policyholder) / Date  
& Time



Witnessed by Reporting Centre  
Personnel



# CERTIFICATE OF INSURANCE

## KIA AUTO PROTECTOR PRIVATE VEHICLE

**Name of Policyholder** : TAY HEAN CHEOW (ZHENG XIANZHAO)  
**Period of Insurance** : 11 Mar 2019 To 10 Mar 2021  
**Engine No.** : G4FGJH716076  
**Chassis No.** : KNAF3416MK5027526

**Vehicle No.** : SMJ5395X  
**Policy No.** : 1900017500  
**Endorsement No.** :  
**Issued Date** : 15 Mar 2019

### ABOUT THE COVER

**Make/Model** : KIA Cerato  
**Engine Capacity/Tonnage** : 1,591.00 CC  
**Driver Restriction** : NA  
**Sum Insured** : Market Value  
**Off Peak Car** : No  
**First Year of Registration** : 2019  
**Insuring with COE/PAFF** : Yes

#### Person or Classes of Persons Entitled to Drive\* :

- a) The Policyholder  
 b) Any other person who is driving on the Policyholder's order or with his/her permission.  
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

**Age Condition** : All Age Condition

#### Limitation as to use\* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.  
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

**Loss of Use 1500cc - 1600cc**

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

### EXCESS

**Section 1**  
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

**Section 2**  
 Property Damage - \$0

**Windscreen** : \$100

**Named Driver and Excess (where applicable)**

TAY HEAN CHEOW (ZHENG XIANZHAO) - \$600 (Own Damage)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 675733 69328000
2. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.com.sg](http://www.aig.com.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

### IMPORTANT NOTES

**Hire Purchase Company/Employer's Loan:** Daimler Financial Services Africa & Asia Pacific Ltd

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504622245

CYCLE & CARRIAGE-JEDD

239 ALEXANDRA ROAD  
 SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

**AIG Asia Pacific Insurance Pte. Ltd.**  
 AUTHORISED REPRESENTATIVE

SSCSAN