

ASS. REC. BY:

Steve

REF:

A/G

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

SIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Turn Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No:

SMT 724C

Yr Regn:

15/7/20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi Atrage

c.t. 1193

Colour:

Red

A/C: Insured / Std / NI / N

Sp. Reading

4864

T/Radio: Insured / Std / NI / N

Eng/No:

MMRSTA BAKH 000 3375

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

185/55R15

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

5

mm

Rear

R/Bal.

5

mm

U/Bal.

5

mm

U/Bal.

5

mm

D.O.A.

7/2/21

D.O.I.

8/2/21

Survey held at

cycle & carriage

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

MV- 66K

Date/Time, File, Pass to?



: Prel. Report



: Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:



: Site Insp (\$ _____)



: Interview (\$ _____)



: Tech. Invs (\$ _____)



: Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Approved:

Signature / Date:



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info
CHEN THIM KWANG 14 ANG MO KIO CENTRAL 3 #12-23 SINGAPORE 567747 Contact No Mobile: 96731859	Cust No/Name /CHEN THIM KWANG Reg No/Reg Date SMT7211C / 15/07/202 Date In/Mileage / 0 Chassis No MMBSTA13AKH003375 Engine No 3A92UJB1449 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	08/02/2021/ 12:34		442 / CocoLu	62792			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER, BOOTLID, REAR LAMP HOUSING RH, REAR END PANEL REAR AIRDAM, REPAIR REAR, FENDER LH, REAR COMPARTMENT, REAR FENDER RH					5 X 450			2250.00
E PNT88000 REMOVE & INSTALL REAR AIR DAM								100.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR								60.00
E PNT88000 REMOVE & INSTALL REAR COMARTMENT TRIMS								300.00
E PNT98000 SPRAY PAINT FOR REAR AIRDAM, REAR BUMPER, REAR END PANEL, BOOTLID REAR COMPARTMENT, REAR LAMP HOUSING RH & LH, REAR FENDER RH & LH					6 X 350			3150.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTION								80.00
M SUNDRY C&C LOGO								40.00
M SUNDRY SUPPLY PARKING SENSOR								220.00
M SUNDRY Sundry								20.00
M UNPAINTED BODYKITS					1.00	1643.00	00.00	1643.00
M FACE, RR BUMPER					1.00	748.00	00.00	748.00
M BRACKET, RR BUMPER, RH					1.00	28.00	00.00	28.00
M BRACKET, RR BUMPER, LH					1.00	28.00	00.00	28.00
M PANEL, RR COMB LAMP HSG, RH					1.00	60.00	00.00	60.00
M PANEL, RR COMB LAMP HSG, LH					1.00	60.00	00.00	60.00
M PANEL, RR END					1.00	425.00	00.00	425.00
M PANEL, TRUNK LID					1.00	791.00	00.00	791.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
CHEN THIM KWANG 14 ANG MO KIO CENTRAL 3 #12-23 SINGAPORE 567747 Contact No Mobile: 96731859	Cust No/Name /CHEN THIM KWANG Reg No/Reg Date SMT7211C / 15/07/202 Date In/Mileage / 0 Chassis No MMBSTA13AKH003375 Engine No 3A92UJB1449 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	08/02/2021/ 12:34		442 / CocoLu	62792			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	WEATHERSTRIP, TRUNK LID	X			1.00	157.00	00.00	157.00
M	HINGE, TRUNK LID, RH				1.00	203.00	00.00	203.00
M	HINGE, TRUNK LID, LH				1.00	203.00	00.00	203.00
M	HINGE, TRUNK LID, LH				1.00	218.00	00.00	218.00
M	LATCH, TRUNK LID				1.00	218.00	00.00	218.00
M	LATCH, TRUNK LID				1.00	336.00	00.00	336.00
M	GARNISH, RR END PANEL	X			1.00	69.00	00.00	69.00
M	MARK, THREE-DIA	npc			1.00	21.00	00.00	21.00
M	MARK, ATTRAGE	npc			1.00	66.00	00.00	66.00
M	TRIM, RR END	CRU			1.00	195.00	00.00	195.00
M	BOARD, TRUNK ROOM FLOOR	BR			1.00	160.00	00.00	160.00
M	TRIM, TRUNK ROOM SIDE, RH	X			1.00	23.00	00.00	23.00
M	REFLECTOR	X			1.00	23.00	00.00	23.00
M	REFLECTOR	X			1.00	23.00	00.00	23.00
M	LAMP ASSY, COMB, RR RH	CRU			1.00	335.00	00.00	335.00
M	LAMP ASSY, LICENSE PLATE	X			1.00	51.00	00.00	51.00

Estimate

Steve (LKK) 8/2/21, 3.00pm

00-NH ALL

Excess - ?

PIP

My BL SK

7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Confirm & accepted by

Nett 12,213.00
7% GST on 12213.00 854.91
Total Payable 13,067.91

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	08/02/2021 13:38 (SGT)
Date of Accident	07/02/2021 11:23 (SGT)
Exact Location of Accident	BKE, Singapore
Additional Location Information	AROUND 300M FROM WOODLANDS EXIT ON BKE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMT7211C
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	CHEN THIM KWANG
NRIC No	SXXXX897I
Email Address	THIMKWANGCHEN@YAHOO.COM.SG
Mobile Phone No	(Phone) +65-96731859
Alternative Phone No	+65-96731859

VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Attrage
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	2070106224
Cover Note Number	-

DRIVER

Name of Driver	CHEN YEW YEN IAN
NRIC No	TXXXX455F
Date Of Birth	20/07/2000
Occupation	Indoor

Or Driving Pass
 Driving experience
 Gender
 Mobile Number
 Alt. Phone Number
 Email Address
 Address
 Address complement
 Postcode
 Is the driver the policyholder?
 If No, Relationship of the Driver with the Insured
 Does Driver Own Other Vehicles?
 Vehicle Registration Number of Other Vehicle Owned by Driver
 Insurance Company of Other Vehicle Owned by Driver

08/12/2019
 1 YEAR AND 2 MONTHS
 Male
 (Phone) +65-97815628
 -
 IANCHENYEWYEN@HOTMAIL.COM
 14 ANG MO KIO CENTRAL 3 #12-23
 -
 567747
 No
 Child
 No
 -
 -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
 Weather Conditions
 Road Surface

Collision - Head to Rear
 Clear
 Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
 Number of vehicles involved in the accident
 Was anybody injured in the Accident?
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged?
 Number of Passengers (Including Driver)
 Has the driver been approached by unknown person(s)
 soliciting/offering accident claims assistance?

No
 2
 No
 -
 Yes
 1
 No

DETAILS OF POLICE ACTION

Was the accident reported to the police?
 Was notice of intended Prosecution given?
 If yes, against whom?

No
 No
 -

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?
 Was there any video captured by Car Camera?
 Was there any audio recorded?

Yes
 Yes
 No

DETAILS OF OTHER VEHICLE PROPERTY 1:

Vehicle Registration Number
 Vehicle Manufacturer
 Vehicle Model
 Vehicle Variant
 Vehicle Colour
 Vehicle Category
 Name of Driver
 Contact Number
 Address
 Address complement
 Postcode
 Insurance Company Name

SMG2464R
 Nissan
 Sylphy
 -
 White
 Private car
 LAU HON KIN
 (Phone) +65-98002987
 -
 -
 -
 -

Amount Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:


(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 10:20am
8 Feb 2021
Policyholder's Signature / Date & Time

 8/2 1025H
Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan



A: SMT 7211C
B: SUG 2464R

Describe Circumstances of the Accident

I was travelling on the 2nd ~~lane~~ lane on the BKE, around 300m from the woodlands exit. As per usual, when the car in front brakes, I brake. ~~At this point, the car in front of me suddenly stopped.~~ Suddenly, the car behind hit me from the back.

Declaration

We declare the foregoing particulars are true in every respect.



8 Feb 2021
10:20 am

Policyholder's Signature / Date & Time



8/2

1027H

Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

CERTIFICATE OF INSURANCE

CYCLE & CARRIAGE AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : CHEN THIM KWANG
Period of Insurance : 15 Jul 2020 To 14 Jul 2022
Engine No. : 3A92UJB1449
Chassis No. : MMBSTA13AKH003375

Vehicle No. : SMT7211C
Policy No. : 2070106224
Endorsement No. :
Issued Date : 28 Jul 2020

ABOUT THE COVER

Make/Model : MITSUBISHI ATTRAGE 1.2 CVT
Engine Capacity/Tonnage : 1,193.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : Yes
First Year of Registration : 2020
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive* :

- The Policyholder
 - Any other person who is driving on the Policyholder's order or with his/her permission.
- This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Mileage Condition : Unlimited Mileage

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

CHEN THIM KWANG - \$600 (Own Damage), \$600 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

- Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
- Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
- Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 20 Leng Kee Rd Singapore 159094 64708688
- Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HL Bank

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504675224

CYCLE & CARRIAGE - ANYONG

239 ALEXANDRA ROAD
 SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

This computer generated document does not require a signature.

SSCZSS

1003494933/AC4/Decal