

ASS. REC. BY:

REF: CS/MSG21001862/Kqf3

Special Instruction:

Surveyor: KENNETH

ASSIGNMENT (Office)

From (Person): JOWYN TAY MEI LING of MSIG Date/Time: 08 Feb 2021 15:34

Estimated Cost: Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJJ 5806M Insured: SLN 8801L

at Workshop m/s MBM Wheelpower Pte Ltd Tel: 6262 8888

of 160 Sin Ming Drive #06-02, Sin Ming AutoCity, 575722 Sin Ming

Policy No: 30001622415 Claim No: 253115

Sum Insured: Excess:

Make of Veh: D.O.A. 04/02/2021
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 08-02-21 5.47P.M

Person Contacted: SHIRLEY

Vehicle IN ☒ OUT

Date/Time	Action/Instruction (☒) Estimate
	SJJ 5806M- CC6/AIG13001742/T1b1a3q2 DOA :22/01/2013
	SLN 8801L- ☒