

ASS. REC. BY:

Steve

REF:

A16

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_


Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_

Consistent? : Yes or No

SIA / PR Sent: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

days

Res.: Yes or No

Turn Sum: \_\_\_\_\_

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: \_\_\_\_\_

SFQ 3361C

Yr Regn: \_\_\_\_\_

31/7/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: \_\_\_\_\_

KIA NITRO

c.t. \_\_\_\_\_

1580

Colour: \_\_\_\_\_

Blue

A/C: Insured / Std / NI / N

Sp. Reading \_\_\_\_\_

50338

T/Radio: Insured / Std / NI / N

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

KNACC 81:EVH 5094 924

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: \_\_\_\_\_

F: \_\_\_\_\_

205/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

R/Bal. \_\_\_\_\_

S

mm

Rear

R/Bal. \_\_\_\_\_

S

mm

U/Bal. \_\_\_\_\_

S

mm

U/Bal. \_\_\_\_\_

S

mm

D.O.A. \_\_\_\_\_

6/2/21

D.O.I. \_\_\_\_\_

8/2/21

Survey held at \_\_\_\_\_

Clyck &amp; Carriage

Des. of Damages: Frt / (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

MV-738

Date/Time, File, Pass to?

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐

Site Insp (\$ \_\_\_\_\_)

☐

Interview (\$ \_\_\_\_\_)

☐

Tech. Insp (\$ \_\_\_\_\_)

☐

Wash and (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS \$ \_\_\_\_\_

Photos

Others

TOTAL

Signature:

Date/Time, File, Return to?



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Toh Hun Hoe Benjamin Reg No/Reg Date SFQ3361C / 31/07/201 Date In/Mileage / 0 Chassis No KNACC81CVH5094024 Engine No G4LEHS215680 Make/Model KIA/NIRO 1.6 A Colour/Trim C3U DEEP CERULEAN B/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	08/02/2021/ 10:45	QUD	247 / DonBong	28674
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW ACCIDENT DAMAGED PARST ON REAR BUMPER FACE, REPAIR REAR END PANEL				400 1200.00
E PNT88000	REMOVE AND INSTALL PARKING SENSOR				60.00
E PNT98000	PAINT WORK SPRAY REAR END PANEL, REAR BUMPER FACE AND AFFECTED PORTION				350 1050.00
M SUNDRY	APPLY BODY SEALANT				80.00
A 54900099	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				30.00
M SUNDRY	PERFORM RUST PREVENTION				80.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY	SUPPLY REAR NUMBER PLATE WITH FRAME				50.00
M SUNDRY	SUNDRIES				20 50.00
M	BRACKET ASSY-RR BUMPER SIDE, LH	1.00	25.00	20.00	20.00
M	BRACKET ASSY-RR BUMPER SIDE, RH	1.00	25.00	20.00	20.00
M	STAY-RR BUMPER LH	1.00	67.00	20.00	53.60
M	STAY-RR BUMPER RH	1.00	67.00	20.00	53.60
M	BRACKET-RR BEAM UPR MTG, LH	1.00	6.00	20.00	4.80
M	BRACKET-RR BEAM UPR MTG, RH	1.00	6.00	20.00	4.80
M	ANTENNA ASSY-SMARTKEY	1.00	39.00	20.00	31.20
M	BEAM-RR BUMPER	1.00	261.00	20.00	208.80
M	BRACKET-RR RAIL LWR MTG	1.00	6.00	20.00	4.80
M	BRACKET-RR BEAM LWR, CTR	1.00	6.00	20.00	4.80
M	BRACKET-SMART KEY MTG	1.00	5.00	20.00	4.00
M	WIRING HARNESS-RR BUMPER	1.00	361.00	20.00	288.80

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/Toh Hun Hoe Benjamin
	Reg No/Reg Date	SFQ3361C / 31/07/201
	Date In/Mileage	/ 0
	Chassis No	KNACC81CVH5094024
	Engine No	G4LEHS215680
	Make/Model	KIA/NIRO 1.6 A
	Colour/Trim	C3U DEEP CERULEAN B/ WK SATURN BLACK

					WIP No			
Account No	Terms	Date/Time Printed	CSE	Operator				
LAX00000	Credit	08/02/2021/ 10:45	QUD	247 / DonBong	28674			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	REFLECTOR/REFLEX ASSY-RR RH	!			1.00	104.00	20.00	83.20
M	COVER-RR BUMPER,UPR	?			1.00	486.00	20.00	388.80
M	COVER-RR BUMPER LWR	/ CNT			1.00	392.00	20.00	313.60
M	PIECE-RR BUMPER SIDE,RH	/ CNT (Silver)			1.00	16.00	20.00	12.80
M	SENSOR ASSY-PARKING ASSIST SYS	?			1.00	135.00	20.00	108.00
M	SENSOR ASSY-PARKING ASSIST SYS	X			1.00	135.00	20.00	108.00
M	SENSOR ASSY-PARKING ASSIST SYS	X			1.00	135.00	20.00	108.00
M	SENSOR ASSY-PARKING ASSIST SYS	X			1.00	135.00	20.00	108.00
M	SKID PLATE-RR BUMPER	/ CNT			1.00	122.00	20.00	97.60

# Estimate

SURVEYOR NAME: Steve (CLKK) 8/2/21, 10:30 onSURVEYOR SIGNATURE: WHL P/LDATE: P/PREMARKS: Ry Bel spy  
3 days

LKK Auto Consultants hence notify  
the Repairer of the following:

• To resurvey before/after spray painting

Confirm & accepted by display damaged part(s) during resurvey

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

	<b>Nett</b>	<b>4,747.20</b>
<b>7% GST on</b>	<b>4747.20</b>	<b>332.30</b>
<b>Total Payable</b>		<b>5,079.50</b>

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission .....  
Date of Accident .....  
Exact Location of Accident .....  
Additional Location Information .....  
Country/State of Loss .....

08/02/2021 10:16 (SGT)  
06/02/2021 08:43 (SGT)  
Jln Anak Bukit, Singapore  
JALAN ANAK BUKIT  
Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number .....

SFQ3361C

### INSURED/POLICYHOLDER

Is company? .....  
Name Of Registered Owner .....  
NRIC No .....  
Email Address .....  
Mobile Phone No .....  
Alternative Phone No .....

No  
TOH HUN HIE BENJAMIN  
SXXXX658H  
TOHTEO@YAHOO.COM.SG  
(Phone) +65-93547270  
+65-93547270

### VEHICLE PARTICULARS

Manufacturer .....  
Model .....  
Variant .....  
Exact purpose for which vehicle was being used at time of accident .....  
Are you claiming under your own insurance policy for repair to your vehicle? .....  
Vehicle Category .....

Kia  
Niro  
-  
-  
No - Claiming third party  
Private car

### INSURANCE COMPANY

Name of Insurance Company .....  
Type of Coverage .....  
Fleet Policy .....  
Policy Number .....  
Cover Note Number .....

AIG  
Comprehensive  
No  
1700034272  
-

### DRIVER

Name of Driver .....  
NRIC No .....  
Date Of Birth .....  
Occupation .....

TOH HUN HIE BENJAMIN  
SXXXX658H  
23/05/1959  
Indoor

Date Of Driving Pass	21/01/1981
Driving experience	40 YEARS AND 1 MONTH
Gender	Male
Mobile Number	(Phone) +65-93547270
Alt. Phone Number	+65-93547270
Email Address	TOHTEO@YAHOO.COM.SG
Address	52A TOH TUCK ROAD #03-02
Address complement	-
Postcode	596744
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO ATTACHMENT

##### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number	SLC3330Y
Vehicle Manufacturer	Audi
Vehicle Model	A3
Vehicle Variant	-
Vehicle Colour	White
Vehicle Category	Private car
Name of Driver	AGNES ONG BEE YEN
Contact Number	(Phone) +65-97897076
Address	-
Address complement	-
Postcode	-
Insurance Company Name	AIG

Vehicle Of Damage \*  
Details of property damaged in accident \*  
No. Of Passenger (Including Driver) \*



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time  
8/02/21 0830

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

### Sketch Plan



Describe Circumstances of the Accident


Refer attachments.

#### Declaration

We declare the foregoing particulars are true in every respect.

\_\_\_\_\_  
Policyholder's Signature / Date &  
Time

\_\_\_\_\_  
Driver's Signature (If driver is not the policyholder) / Date  
& Time

  
\_\_\_\_\_  
Witnessed by Reporting Centre  
Personnel



I was driving and going straight in the centre lane of 3-lane Jalan Anak Bukit towards Dunearn Road on Saturday, 6 Feb 21, at about 8:43am. The road was dry and the weather was fine. Traffic on Jalan Anak Bukit was heavy and slow moving that morning. I had stopped my car behind a light goods commercial vehicle in the slow moving traffic and a short moment later a white Audi A3 car (SLL3330Y) knocked into the rear bumper of my car (SFQ3361C). After accident review of my in-car rear camera showed that the white Audi A3 (SLL3330Y) was on the extreme left lane of Jalan Anak Bukit and was trying to filter to the extreme right lane.

TK

8 Feb 21

0830

## AIG AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : TOH HUN HOE BENJAMIN  
Period of Insurance : 31 Jul 2020 To 30 Jul 2021  
Engine No. : G4LEHS215680  
Chassis No. : KNACC81CVH5094024

Vehicle No. : SFQ3361C  
Policy No. : 1700034272-03  
Endorsement No. :  
Issued Date : 26 Jun 2020

### ABOUT THE COVER

Make/Model : KIA Niro 1.6

Engine Capacity/Tonnage : 1,580.00 CC

Driver Restriction : NA

Sum Insured : Market Value

Off Peak Car : No

First Year of Registration : 2017

Insuring with COE/PAFF : Yes

Person or Classes of Persons Entitled to Drive\* :

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use\* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

### EXCESS

#### Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

#### Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

TOH HUN HOE BENJAMIN - \$600 (Own Damage), \$600 (Flood Cover)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501

2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000

3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800

4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.sg](http://www.aig.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HL Bank

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0500709926

CYCLE & CARRIAGE - CINDY

239 ALEXANDRA ROAD

SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

**AIG Asia Pacific Insurance Pte. Ltd.**

This computer generated document does not require a signature.

AIGSGMOBILEAPP

1003405240/AC