



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	TPVD (SGZ35E)
Date of Loss	6 February 2021
Time of Loss	11.15
Loss Description	SHA2667M (INSD) C/W SGZ35E (TP)
Comment	<input type="text"/>

Workshop Details

Total Rebate Amount	<input type="text" value="32169"/>
Nett Loss Amount	\$29,831.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	<input type="text" value="20"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details



Vehicle Registration#	SGZ35E	Purchase Date	<div>dd/mm/yyyy</div> <div></div>
Registration State	<div>SINGAPORE</div>	Registration Date *	<div>18/03/2010</div> <div></div>
Mileage	<div>383093</div>	Age of Vehicle	10

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		<div>2010</div>
Make	TPVD	<div>TOYOTA</div>
		<div></div>

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	NEO THHUAN HING	<div></div>
Date of Birth		<div>dd/mm/yyyy</div> <div></div>

Model CATEGORY	POLICY INFORMATION	PREVIA 8 SEATER ASSESSMENT INFORMATION
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="JTEGD52M20A019445"/>
Engine No		<input type="text" value="2AZH469828"/>
Engine Capacity		<input type="text" value="2362"/>
Sum Insured		<input type="text" value="0"/>
Market Value		<input type="text" value="62000"/>

CATEGORY Age	FNOL INFORMATION 0	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="dd/mm/yyyy"/> 
License Expiration Date		<input type="text" value="dd/mm/yyyy"/> 

CATEGORY	FNOL INFORMATION	POST SURVEY
Address	Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="▼"/>
Gender	Unknown	<input type="text" value="▼"/>
Marital status	Unknown	<input type="text" value="▼"/>
Identification #	TBC	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

17/02/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver
Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

Rear Tyre Size

Front left side

Rear left side

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text"/>	Salvage%	<input type="text"/>
Discount%	<input type="text" value="25"/>	Settlement%	<input type="text" value="100"/>

Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Paint Material Ratio	<input type="text" value="80"/>
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

YesNo

Part Supplied by AXA

YesNo

Save



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts






Add

Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REAR BUMPER	Deformed	0	534.9	No		25			401.18	Reviewing
<input type="checkbox"/>		0	2		REAR BUMPER SIDE HOLDER	Necessary	0	55.9	No		25			83.85	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER TOW COVER	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	2		REAR BUMPER REFLECTOR	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		REAR END PANEL	Dented	0	625.5	No		25			469.13	Reviewing
<input type="checkbox"/>		0	1		REAR END PANEL TOP GARNISH	Cracked	0	295.2	No		25			221.4	Reviewing
<input type="checkbox"/>		0	1		TAILGATE	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		TAILGATE LOCK	Serviceable	0	0	No		25			0	Deny

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		TAILGATE WEATHERSTRIP	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		TAILGATE GLASS MOULDING	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		TOYOTA LOGO	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		TOYOTA WORDING	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		PREVIA WORDING	Serviceable	0	0	No		25			0	Deny







Labour



Add

Approve

Deny

Submit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		PANEL BEATING, REMOVE AND REFIT PARTS	0	600	0	0	Reviewing	
<input type="checkbox"/>		0		SPRAY PAINTING TO AFFECTED AREA	0	500	0	0	Reviewing	
<input type="checkbox"/>		0		WIRING CHECK	0	30	0	0	Reviewing	
<input type="checkbox"/>		0		TO REMOVE REVERSE SENSOR	0	50	0	0	Reviewing	
<input type="checkbox"/>		0		TO REMOVE UPHOLSTERY	0	60	0	0	Reviewing	
<input type="checkbox"/>		0		TO TRANSFER TAILGATE FITTINGS	0	0	0	0	Deny	

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		TO REMOVE TAILGATE GLASS	0	0	0	0	Deny	
<input type="checkbox"/>		0		TO REMOVE REAR CAMERA	0	0	0	0	Deny	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary




Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	DAYS OF REPAIR : 4 DAYS	Reviewing		0		
<input type="checkbox"/>		0	SET REAR BUMPER CLIPS	Reviewing		30	NECESSARY	
<input type="checkbox"/>		0	SET REVERSE SENSOR	Reviewing		200	DAMAGED	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>	0	SET REAR END PANEL TOP GARNISH CLIPS	Reviewing		20	NECESSARY	
<input type="checkbox"/>	0	SET REAR END PANEL SEALANT	Reviewing		60	NECESSARY	
<input type="checkbox"/>	0	TAILGATE GLASS SEALANT	Deny		0	NOT NECESSARY	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount	\$0.00			Adjusted Claim Amount	\$2,725.56		
CATEGORY	ESTIMATE	ADJUSTED					
Spare Parts	\$0.00	\$1,175.56					
Labour	\$0.00	\$1,240.00					
Miscellaneous	\$0.00	\$310.00					

Submit for Review



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>	0	FINAL LUMP SUM	Reviewing		2100		

Submit for Review