

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/196R GS1 Reg. No. 19-900/196-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERAL	_ INSURANCE (S) PL	R	ef:	CS/AGI21001925/Kqf3q2	
	(BUDGET DIRECT 190 CLEMENCEAU SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	D	ate:	16/03/2021	
			C	ode:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SKG 7611Z	Veh. Inspected		SLT 1826E	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10008953/JM	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		09/02/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA C-HR (A)	c.c		1797	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	ZYX102055892	Colour		METALLIC BLUE	
	Odometer	233660 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/60 R17	SUNWIDE		9 mm	
	L/H Front Tyre	215/60 R17	SUNWIDE		9 mm	
	R/H Rear Tyre	215/60 R17	SUNWIDE		9 mm	
	L/H Rear Tyre	215/60 R17	SUNWIDE		9 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	05/02/2021	Inspection Date		09/02/2021	
	Survey held at	OPTIMA WERKZ PTE LTD				
		9A SERANGOON NORTH AVE 5 SINGAPORE 554500				
5a.		Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate Days of Repair				

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: