

ASS. REC. BY: Sun Pin

REF:

CS/CT121001927/Qtd3.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____


Policy No. DMPCSNW00135322000Claims No. SNM21D200757/C02/THAMYL

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMN 8063 R Yr Regn: 08/09/2014.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Volkswagen Golf A7. c.c. 1395Colour: Red. A/C: Insured / Std / NI / NASp. Reading: 71493. T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVWZZZ44ZFwo15241.Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 245 / 40 ZR 18R: 245 / 40 ZR 18.BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 30/01/2021 D.O.I. 09/02/2021Survey held at Auto Insure.Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Mv: 41,000</u>
	<u>Pv: 25,547.</u>
	<u>NV: 15,453.</u>
	Finalize amount \$7,700. Repair day 9 days. (L/S, before gst)
	red: 8,116.98; 51%
	15816.98

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L/S: 7700 L/SDays Of Repair: 9Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	033H
Vehicle Details	
Vehicle No.:	SMD8063R
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Feb 2021
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF A7 1.4 TSI AT 5G13GZ W/O HID
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	CXS213274
Chassis No.:	WVWZZZAUZFW015241
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$20,784.00
Original Registration Date:	08 Sep 2014
First Registration Date:	08 Sep 2014
Transfer Count:	1
Actual ARF Paid:	\$6,098.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Sep 2024
PARF Rebate Amount:	\$3,963.00
Intended COE Rebate Details	
COE Expiry Date:	07 Sep 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$60,002.00
COE Rebate Amount:	\$21,584.00
Total Rebate Amount:	\$25,547.00

The information contained herein is correct as at 02 Feb 2021

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 01/02/2021 16:51 (SGT)
Date of Accident 30/01/2021 21:30 (SGT)
Exact Location of Accident Sungei Kadut Dr, Singapore
Additional Location Information -
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMD8063R

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner NG WEI SIANG,DANNY
NRIC No SXXXX033H
Email Address dannyngws@gmail.com
Mobile Phone No (Phone) +65-91815944
Alternative Phone No +65-91815944

VEHICLE PARTICULARS

Manufacturer Volkswagen
Model Golf
Variant -
Exact purpose for which vehicle was being used at time of accident -
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance
Type of Coverage Comprehensive
Fleet Policy No
Policy Number DMPCSNA00120762001
Cover Note Number -

DRIVER

Name of Driver NG WEI SIANG,DANNY
NRIC No SXXXX033H
Date Of Birth 28/06/1987
Occupation Outdoor

Date Of Driving Pass	04/09/2007
Driving experience	13 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-91815944
Alt. Phone Number	+65-91815944
Email Address	dannyingws@gmail.com
Address	484D CHOA CHU KANG AVE 5 #03-76
Address complement	-
Postcode	684484
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	0
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Choa Chu Kang Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18007659999
Alt. Police Station Phone No	(Fax) +65-67644104
Police Station Address	No 20 Choa Chu Kang Street 52 #01-02 Singapore 689286
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON 30/01/2021, AT ABOUT 2130HRS, I PARKED MY CAR (SMD8063R) ALONG SUNGEI KADUT DRIVE NEAR TO LAMP POST 123R, I ALIGHTED TO HAVE A PUFF OF CIGRETTE AND THERE WAS THIS VAN (GBC5065R) WHO WAS COMING OUT OF GAIN CITY AND DRIVING ALONG SUNGEI KADUT DRIVE. AT THIS INSTANCE, THERE WAS A WHITE CAR (SJM1981A) WHO WAS SPEEDING ALONG SUNGEI KADUT DRIVE FAILED TO NOTICE THE WHITE VAN. THE DRIVER OF THE WHITE CAR TRIED TO AVOID THE VAN THUS HE COLLIDED INTO THE SIDE OF MY VEHICLE. AFTER THE ACCIDENT, AMBULANCE AND TRAFFIC POLICE WAS DISPATCHED TO THE SCENE AND RECORDED OUR PARTICULARS. I WISH TO STATE THAT MY CAR COULD NOT BE DRIVEN AFTER THE ACCIDENT I AM NOT INJURED. I DO NOT HAVE ANY DASHCAM INSTALLED IN MY VEHICLE. I WISH TO STATE THAT AFTER THE COLLISION, THE IMPACT WAS TOO HUGE CAUSED MY VEHICLE MOUNT ONTO THE KERB AND MY VEHICLE LEFT HAND SIDE WAS DAMAGE TOO.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJM1981A
-----------------------------------	----------




Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	(Phone) +65-92261981
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBC5065R
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Goods vehicle
Name of Driver	-
Contact Number	(Phone) +65-97506424
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

Along Sungai Kadul Ave



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report

7/08/2018 31/08/2018

I wish to stated after the collision. the impact was too huge caused my vehicle mount onto the kerb and my vehicle left hand side was damage too.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Auto Insure Pte. Ltd
6 Marsiling Lane
739145



Insurer Reference: SMD8063R
Repairer Reference: M1562 / SMD8063R
Date calculated: 03/02/2021 12:16 PM

Full Report
Registration: SMD8063R
Printed: 03/02/2021 12:16 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Min Seng Chong	Currency:	SGD
Claim Reference:	SMD8063R	Date of Incident:	30/01/21
Estimated Repair Time:	9	Hire Car Start:	
Actual Repair Days:	9	Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	VW
Model:	GOLF (5G)
Sub Model:	BASE MODEL
Model Sheet Number:	06 B1 23
Registration:	SMD8063R
VIN number:	WVWZZZAUZFW015241
Odometer:	71493

Model Specs

FROM 06/2014	OCCUPANT PROTECT SYS	BLUE MOTION TECHNO	CHROME PACKAGE
CLIMATRONIC	D/MIRROR W/AMBIENT	LIGHT-/RAIN SENSOR	FRT/RR ELECT WINDOWS
AUTO DIPPING MIRROR	8 SPEAKER	RADIO "COMP COLOUR"	FOG LAMPS
LIGHT SWITCHING AUTO	CLOTH TRIM	HEIGHT ADJ PASS SEAT	STRG WHEEL LEATHER
MULTI FUNC INDICATOR	LUMBAR SUPPORT	STOP-START SYSTEM	FRONT CENTRE ARMREST
REAR CENTRE ARMREST	SMOKER EQUIPMENT	ALTERNATOR 140A	HD COOLING
1.4 LTR 90KW	7-SPEED DSG	SELECT DRIVE	TYRES 205/55 VR 16
WHEELS 6.5J X 16 ALU	SPACE SAVER SP-WHEEL	RR DUAL EXHAUST PIPE	5-DOOR
CRUISE CONTROL	TWO COAT METALLIC		

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
66 05 19 00	R + R RADIATOR GRILLE		2.0	8.40
63 29 19 50	R + R FRONT BUMPER COVER (RADIATOR GRILLE REMOVED)		4.0	16.80
63 29 55 51	RENEW FRONT BUMPER COVER (REMOVED)		12.0	50.40
	INCLUDES: CONVERT ATTACHED PARTS			
94 15 19 50)	R + R RIGHT HEADLAMP (RADIATOR GRILLE REMOVED) (FRONT BUMPER COVER DETACHED OR REMOVED)		1.0	4.20
	DOES NOT INCLUDE: ADJUST HEADLAMPS			
50 55 19 50	R + R RIGHT FRONT WING (BUMPER COVER REMOVED) INCLUDES: R + R WHEEL AND WHEELHOUSE SHELL		7.0	29.40
50 55 51 50	R/F WING SEAL (COMPOSITE WORK)		3.0	12.60
92 25 20 00	R + R WIPER ARMS		4.0	16.80
66 44 20 50	R + R COWL TRIMS (WIPER ARMS REMOVED)		3.0	12.60
57 51 19 00	R + R RIGHT FRONT DOOR		3.0	12.60
57 51 55 50	RENEW RIGHT FRONT DOOR (DOOR REMOVED) INCLUDES: R + R ALL PARTS		24.0	100.80
63 69 55 50	RENEW REAR BUMPER COVER (BUMPER REMOVED) INCLUDES: CONVERT ATTACHED PARTS		4.0	16.80
53 55 53 00	R/SIDE SECTION (REMOVAL OF PARTS) INCLUDES: REMOVE TAILLAMPS, BUMPER COVER, WHEELHOUSE LINER, SIDE TRIM, SEAT CUSHION, SEAT BACKREST, INNER SILL		11.0	46.20

Code	Description	WU	Price SGD
	MOULDING, LOCK PLATE, C-PILLAR TRIM, BOOT COVER, SEAT BELT, BOOT COVER GUIDES AND BOOT TRIM		
53 55 55 00	RENEW RIGHT SIDE PANEL	74.0	310.80
53 55 59 00	ASSEMBLE R/SIDE PANEL PARTS INCLUDES: DISMANTLED PARTS FIT IF NECESS RENEW, LIGHT CHECK	16.0	67.20
53 56 55 50)	RENEW R/LOWER SIDE PANEL (COMP WORK)	25.0	105.00
48 79 19 50)	R + R RIGHT FRONT TIE ROD (WHEEL REMOVED)	2.0	8.40
46 14 19 50)	R + R RIGHT FRONT BRAKE CALIPER CARRIER	4.0	16.80
40 85 19 50)	R + R R/F SPRING STRUT (WHEEL AND COWL TRIM REMOVED)	4.0	16.80
40 90 19 50	R + R RIGHT FRONT SHOCK ABSORBER (SPRING STRUT REMOVED) INCLUDES: R + R SPRING STRUT MOUNT AND COIL SPRING	4.0	16.80
40 50 19 50	R + R R/F WHEEL BEARING HOUSING (WHEELS REMOVED) INCLUDES: R + R SPEED SENSOR AND BRAKE DISC, DETACH + REFIT DRIVE SHAFT	7.0	29.40
40 50 55 50	RENEW R/F WHEEL BEARING HOUSING (WHEEL BEARING HOUSING REMOVED) INCLUDES: R + R WHEEL BEARING AND WHEEL HUB	4.0	16.80
40 07 19 00)	R + R ASSEMBLY CARRIER (WHEELS AND SOUND PROTECTION PAN REMOVED) INCLUDES: DETACH + REFIT LOWER AXLE RADIUS ARMS DOES NOT INCLUDE: ALIGN FRONT AND REAR	14.0	58.80
40 07 55 50	RENEW AGGREGATE CARRIER (REMOVED)	6.0	25.20
46 15 19 50)	R + R RIGHT REAR BRAKE CALIPER CARRIER	1.0	4.20
42 93 19 50)	R + R RIGHT REAR SHOCK ABSORBER	2.0	8.40
42 11 19 50)	R + R R/R LOWER CONTROL ARM (WHEEL AND COIL SPRING REMOVED) (CONTROL ARM DETACHED)	2.0	8.40
42 35 19 50)	R + R R/R UPPER CONTROL ARM (WHEEL AND COIL SPRING REMOVED) (CONTROL ARM DETACHED)	1.0	4.20
42 05 19 00)	R + R REAR AXLE (WHEELS REMOVED) INCLUDES: COIL SPRINGS REMOVE AND REFIT BRAKE PIPES, BRAKE CALIPERS AND S-ABSORB DETACH + REFIT WITHOUT: BLEED BRAKE SYSTEM	24.0	100.80
42 05 55 50	RENEW REAR AXLE MEMBER (REMOVED) INCLUDES: CONVERT ATTACHED PARTS	16.0	67.20
47 01 07 50	BLEED BRAKE SYSTEM	3.0	12.60
01 50 00 ZAX	GFS / GUIDED FUNCTION (READ AND DELETE ERROR MEMORY AFTER REPAIR)	2.0	8.40
44 95 03 00	ALIGN FRONT AND REAR VEHICLE	10.0	42.00

Code	Description	WU	Price SGD
94 15 06 00	INCLUDES: CHECK TOE AND CAMBER, R + R BRACKET AND ALIGNMENT SENSOR DOES NOT INCLUDE: ADJUSTMENT ADJUST HEADLAMPS	3.0	12.60
0741	INCLUDES: ADJUST FRONT FOG LAMPS L/F WING REPAIR	10 20.0*	84.00
1782	R/R DOOR REPAIR	10 20.0*	84.00
2140	R/OUTER SILL PANEL REPAIR	20 30.0*	126.00
7036	R/DRIVE SHAFT CHECK		
Labour Cost		Hrs	WU
Panel / Mechanical Labour		36.20	362.0
Alignment			
Measuring Work		1.00	10.0
Total of Labour			1,562.40

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC	WU	Price SGD
	R/F WING NEW PART PAINTING	9.0	
	RIGHT FRONT DOOR NEW PART PAINTING	16.0	
	R/SIDE PANEL NEW PART PAINTING	24.0	
	FRONT BUMPER COVER NEW PART PAINT K1R	11.0	
	REAR COVER BUMPER NEW PART PAINT K1R	12.0	
	L/F WING REPAIR PAINTING >50%	14.0	
	R/R DOOR REPAIR PAINTING >50%	21.0	

Paint Material Per Part

Code	Description	Price SGD
0742	R/F WING NEW PART PAINTING	15.48
1482	RIGHT FRONT DOOR NEW PART PAINTING	43.34
3482	R/SIDE PANEL NEW PART PAINTING	30.80
0283	FRONT BUMPER COVER NEW PART PAINT K1R	52.64
2583	REAR COVER BUMPER NEW PART PAINT K1R	56.09
0741	L/F WING REPAIR PAINTING >50%	11.85
1782	R/R DOOR REPAIR PAINTING >50%	25.68

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor			
Time Paint		107.0	
Preparation Main Work Metal	2.10	21.0	88.20
Preparation Comp. Work Plastic	0.50	5.0	21.00
Total	10 WU/h	133.0	558.60

Material Cost - Paint

New Part Painting	Price SGD
New Part Painting - Plastic K1R	89.62
Repair Painting	108.73
Material-constant Metal	37.53
Material-constant Plastic	18.10
Total	9.00
	262.98

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Part Source	Price SGD
7011	ASSEMBLY CARRIER	5Q0 199 315 Q	Original ?	NN{ 500.00
0283	FRONT BUMPER COVER	5G0 807 217 BN GRU	Original /CRU.	✓ 600.00
0299	FRT CTR COWL GRILLE	5G0 853 677 H 9B9	Original ?	NN{ 135.00
0393	FRT SPOILER BRACKET	5G0 805 915 9B9	Original ?	NN{ 160.00
0319	L/F OUT BUMPER BRKT	5G0 807 723 D	Original /X	NN{ 15.00
0843	L/F W-HOUSE FRT CVR	5G0 805 911 AK	Original X	NN{ 120.00
0297	L/LWR AIR VENT GRILL	5G0 853 665 9B9	Original X	NN{ 75.00
7278	R/ANTI-SQUAT ROD	5Q0 411 315 A	Original ?	bt ✓ 55.00
7062	R/F GUIDE JOINT	5Q0 407 366 A	Original ?	bt ✓ 120.00
0792	R/F NUT	N 908 173 02	X SVC	0.00
0320	R/F OUT BUMPER BRKT	5G0 807 724 D	Original /Bh	15.00
7096	R/F S-ABSORB BRACKET	5Q0 412 249 E	Original ?	80.00
7088	R/F SHOCK ABSORBER	5Q0 413 023 FH	Original ?	bt ✓ 200.00
7048	R/F TRACK CONT ARM	5WA 407 152	Original ?	bt ✓ 150.00
7132	R/F WHEEL HUB/BRG	8V0 498 625	Original ?	jam ✓ 280.00
0844	R/F W-HOUSE FRT CVR	5G0 805 912 L	Original /CRU	cru ✓ 120.00
0742	R/F WING	5G0 821 106 A	Original /CRU.	✓ 380.00
9384	R/R AXLE STEERING	5Q0 505 224 D	Original ? bt	✓ 200.00
2618	R/R BUMPER GUIDE	5G6 807 394 A	Original X	NN{ ✓ 25.00
9104	R/R COUPLING ROD	5Q0 505 465 C	Original ?	NN{ 55.00
9386	R/R LWR CONTROL ARM	5Q0 505 311 F	Original ?	nnX{ 150.00
9202	R/R SHOCK ABSORBER	5Q0 513 029 DP	Original ?	nnX{ 200.00
9376	R/R TIE ROD	5Q0 501 529 F	Original ?	nnX{ 80.00
9388	R/R UPP CONTROL ARM	5Q0 505 323 D	Original ?	nnX{ 200.00
9306	R/R WHEEL BRG HSG	5Q0 505 436 F	Original ?	nnX{ 385.00
9182	R/R WHEEL HUB/BRG	5Q0 598 611	Original ?	nnX{ 250.00
3482	R/SIDE PANEL	5G4 809 844	Original X R	820.00
7310	R/TIE ROD	1K0 423 810 A	Original ?	nnx{ 80.00
7312	R/TIE ROD BALL JOINT	1K0 423 812 J	Original ?	nnx{ 90.00
7082	R/WHEEL BEARING HSG	5Q0 407 256 R	Original ?	nnx{ 350.00
2583	REAR COVER BUMPER	5G6 807 417 AP GRU	Original X R	700.00
9081	REAR SUPPORT FRAME	5Q0 505 315 G	Original ?	NN{ 660.00
1482	RIGHT FRONT DOOR	5G4 831 056 AS	Original X R	650.00
0562	RIGHT HEADLAMP ASSY	5G2 941 006 E	Original ?	cra ✓ 885.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings
Subtotal
Total

0.00
8,285.00
8,285.00

Extras

Code	Description	Price SGD
1000	RIM RH FRONT WHEEL / SCR	500.00*
1001	RIM RH REAR WHEEL / SCR.	500.00*
1002	TYRE RH FRONT WHEEL / BR.	250.00*
1003	ALIGNMENT&BALANCING WHEEL / NEC	100.00*
1004	TOWING CHARGES TOWING X	80.00*
	Total Extras	1,430.00

Final Calculation

	SGD	SGD
Parts	8,285.00	
Total Parts		8,285.00
Labour Time Base 10 WU/h		
Total 362.0 WU X 42.00 SGD/h	995.4	1,520.40
Alignment		
Measuring Work		42.00
Total of Labour		1,562.40
Total Of Extras		1,430.00
Paint Work Time Base 10 WU/h		
Labour Cost 133.0 WU X 42.00 SGD/h	596.40	558.60
Material Cost	237.92	262.98
Total Paint Including Material		821.58
Repair Cost Excludes GST		12,098.98
GST (+7.00%)		846.93
Repair Cost Included GST		12,945.91

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair day - 9 days

L/S

After painting photo

09/02/2021.

Sun Pm (LKK)

TP within prequid



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

New 5 Years COE Renewal Toyota Wish 1.8.



2.5% P.A. 0 Down, No Admin,
Monthly From \$688. 2 Year
Warranty - Engine, Gearbox
GV Credit Pte Ltd [StarAd](#)



[» Visit Our Profile «](#)










Browse by Category ▾

Sort by Date Posted ▾ 60 results/page ▾

8 vehicles

Volkswagen Golf

Advanced Search 🔍

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Volkswagen	Golf	Any	Any	2014	Any	Any	Any	Available
	Volkswagen	Golf 1.4A TSI	\$34,600	\$10,720 /yr	17-Jan-2014	1,395 cc	105,000 km	Hatchback	Available
1 Careful Owner! Full Agent Maintained Unit! Showroom Condition! Bank Promo 2.28%! 100% Loan Approval, Loan Up To 100%! Bank/In-House Available. 120 Points Check Done, STA/Agent Evaluation Welcomed. 6 Months Comprehensive Warranty! Full Refund If...									
Golden Charter Pte Ltd									
Posted: 09-Feb-2021 Tags: 2014 Volkswagen Golf, Volkswagen Golf, Volkswagen, Golf									
	Volkswagen	Golf R SDR	\$88,000	\$20,710 /yr	11-Mar-2014	1,984 cc	111,000 km	Sports	Available
Maintained By Reputable Workshop. Selling Due To Changing To Family Car. Number Plate To Be Retained. No Dealers Or Consignments Please.									
Posted: 04-Feb-2021 Tags: 2014 Volkswagen Golf, Volkswagen Golf, Volkswagen, Golf									
	Volkswagen	Golf R SDR Sunroof	\$92,000	\$21,830 /yr	20-Mar-2014	1,984 cc	61,000 km	Sports	Available
Revo IC, Revo Carbon Intake Kit, Revo Throttle And Charge Pipes, Revo Turbo Muffler Delete, Racingline Oil Cooler, Racingline Remote Washer, Miltek Full Catback, Bilstein B16 PSS10, H&R Front/Rear Arbs, Whiteline Front/Rear End Links, Maxton Design Full Bodykit, Rays...									
Posted: 08-Feb-2021 Tags: 2014 Volkswagen Golf, Volkswagen Golf, Volkswagen, Golf									
	Volkswagen	Golf 1.4A TSI	\$38,900	\$10,830 /yr	30-May-2014	1,395 cc	60,000 km	Hatchback	Available
Arguably One Of The Best Golf A7 Around! Ultra Low Genuine/Documented Mileage! Superb Condition! Super Quiet! Buttery Smooth! No Gearbox Issues! New Mechatronics Replaced With Warranty! Buy With Ultimate Peace Of Mind! Used But Definitely Not Abused! Zero Oil...									
Posted: 05-Feb-2021 Tags: 2014 Volkswagen Golf, Volkswagen Golf, Volkswagen, Golf									
	Volkswagen to reveal new Golf R on 4 Nov								
Volkswagen is set to reveal the fifth generation Golf R, with the new model set to be the most powerful and most capable Golf R ever made.									
Read this article									
	Volkswagen	Golf 1.4A TSI	\$38,800	\$10,750 /yr	05-Jun-2014	1,395 cc	77,000 km	Hatchback	Available
2 Owners Only, 100% Loan Available, Very Low Mileage Done! Accident Free, Your Best Entry Level Hot Hatch! Signature White Coat On Stylish Black Upholstery, Condo Parking Last 3 Yr, Comfortable & Spacious, Browse Through Our FB Reviews Below, Only Quality Deal! P...									
Posted: 21-Jan-2021 Tags: 2014 Volkswagen Golf, Volkswagen Golf, Volkswagen, Golf									
	Volkswagen	Golf 1.4A TSI	\$39,888	\$10,540 /yr	28-Aug-2014	1,395 cc	75,000 km	Hatchback	Available
Latest Arrival! 1 Owner, Low Mileage Done At 75000km Guaranteed Non Structural Damage! Well Maintained And Exceptional Unit. 100% Approval Rate. Flexible Loan And Insurance Packages. Call Today To Enquire! STA Evaluation Welcome! Hurry Now Before It's Sold!									
Posted: 06-Feb-2021 Tags: 2014 Volkswagen Golf, Volkswagen Golf, Volkswagen, Golf									
	Volkswagen	Golf 1.4A TSI EQP Sunroof	\$45,800	\$11,380 /yr	30-Sep-2014	1,395 cc	75,500 km	Hatchback	Available
Full Agent Service Record! Low Mileage! Accident Free! No Repair Needed! Road Tax Till Sept 2021! Trade-In Welcome! Call Us Now For Viewing And Test Drive Before It's Gone!									
Posted: 29-Jan-2021 Tags: 2014 Volkswagen Golf, Volkswagen Golf, Volkswagen, Golf									
	Volkswagen	Golf 1.4A TSI	\$41,800	\$10,640 /yr	20-Oct-2014	1,395 cc	117,000 km	Hatchback	Available
One Owner Low Mileage! Accident Free! No Repair Needed! Trade-In Welcome! Call Us Now For Viewing And Test Drive Before It's Gone!									
Posted: 29-Jan-2021 Tags: 2014 Volkswagen Golf, Volkswagen Golf, Volkswagen, Golf									

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

[Compare](#) [view Expired ads](#) 60 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Rental Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Volkswagen Golf, Volkswagen Golf Singapore, used Volkswagen Golf Singapore, used Volkswagen Golf, used vehicles Singapore or even buy used Volkswagen Golf Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2021 sgCarMart, Singapore. All rights reserved.