CC3/AIG2001991/AFF3

ASSIGNMENT

Date:

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / IMV / MV

To Inspect Vehicle No

at Workshop m/s

of

Insured

Policy No

Claim's No: 280584 239684

Sum Insured: Excess: 0

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal or Market Value

IDAC Accident Rport Consistent? : Yes or No

GIA / PR. Seen Consistent? : Yes or No

Est. Repairs 03 days Res.: Yes or No

Lump Sum % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Veh No: SE2222L Year: 2018 April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Audi A6 cc: 1798

Colour: Black A/C: Insured / Std / Nil / NA

Sp Reading: 58925 T/Radio: Insured / Std / Nil / NA

Engl No:

C/No: WAUZZZ4G3JN030135

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/40R19.

R: 255/40R19.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal	06 mm	R/Bal	06 mm
L/Bal	06 mm	L/Bal	06 mm
D.O.A.		D.O.L	10/02/21

Survey held at: Premium.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	OD AIG
	MV : 130K
	PV : 68.1K
	Nett : 61.9K

$5615.68, 3days
(Red: 10,710.32 : 66%)

Date/Time File Passed: ☐ : Preli. Report

☐ : Final Report

Date/Time File Returned:

Days Of Repair: 3

Resurvey No. of Trip:

Total Fee: ☐ : Site Insp. ☐ : Interim ☐ : Final

Survey Fee

Transportation

Other