

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Date/Time: 08.02.2021 12:45

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO: 305452744

TOMER

MS

STOMER NO.

RESS

(R)

(P)

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (O)

SCOUNT CARD NO.


JOB DESCRIPTION

Accident Date: 04.02.2021
NATURE: 3P 04.02.2021

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

CUSTOMER'S SIGNATURE

SERVICE ADVISOR

Acknowledgement Slip

Name:

I/C No.:

Vehicle No.:

SHA3763L

CHIANG

Exit Pass

Vehicle No.:

SHA3763L

Date

Name of Service Advisor

To be kept by Security Guard

Signature/Date

Name of Service Advisor

To be returned to Service Reception upon collection