

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFA 1930Hat Workshop m/s: PERFORMANCEof 303, MICHAMBERAInsured: SMR

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 111K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lam Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SFA 1930H Yr Regn: 2019 / augType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: B.M.W 216 I GRAN TOURER c.c 1499Colour: GRN A/C: Insured / Std / NI / NASp.Reading: 22454 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WBA 6V120905N54314Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/35R17

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 08/02/21

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 20/04/21PERFORMANCE

Date / Time Action / Instruction

Repair limit - 53K

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

S + RS, \$ \_\_\_\_\_

Photos

Others

TOTAL

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Tues 20/04 @ 10am  
S&R ✓

SFA1930H

Dealer

## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

### E S T I M A T E

Estimate No. : b1 57488  
Date Estimated : 08/02/2021  
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -  
Thanaporn Lorchirachoonkul  
59 Hillview Avenue  
#04-05

- ACCOUNT - 40000  
Cash Sales - Service  
Singapore

Singapore 669616

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFA1930H	WBA6V120905N54314	14/08/2019	216i GT	0

#### DESCRIPTION

To replace rear bumper including to knock out dented area caused by the accident

850 1,275.00

To respray rear bumper

934 1,038.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

150 177.00

To check electrical wiring system and lighting at the rear section for proper function.

150 177.00

Sundries

? 80.00

Total Labour 1: 2,747.00

#### DESCRIPTION

RR BUMPER LH SIDE GUIDE ?

QTY PRIC

VALUE

REAR BUMPER CARRIER ?

1 61.65

61.65

SUPPORT ?

1 45.75

45.75

# RR BUMPER LH INNER SIDE GUID ?

1 61.65

61.65

# REAR BUMPER PANEL PRIMED (LI de/

1 1,050.65

1,050.65

REAR BUMPER TRIM STRIP CHROM see/

1 78.75

78.75

Total Parts : 1,758.85



# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 57488  
Date Estimated : 08/02/2021  
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFA1930H	WBA6V120905N54314	14/08/2019	216i GT	0

### Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 20104/21 P1035 Claim No. \_\_\_\_\_  
Date & Time 20/04/21 P1035 Excess S\$ \_\_\_\_\_  
Surveyor's Name Rafael Sign \_\_\_\_\_  
Surveyor's Tel 90022068 Authorised Yes / No  
Authorised Date \_\_\_\_\_ Time \_\_\_\_\_  
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No  
Surveyor's E-mail \_\_\_\_\_  
No. of Working Days Recommend 3 days

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	2,747.00
Parts	:	1,758.85
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	315.41
Grand Total	:	4,821.26

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	09/02/2021 10:56 (SGT)
Date of Accident	08/02/2021 06:50 (SGT)
Exact Location of Accident	Clementi, Singapore
Additional Location Information	ALONG CLEMENTI ROAD TOWARDS ULU PANDAN ROAD
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number SFA1930H

### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	THANAPORN LORCHIRACHOONKUL
NRIC No	SXXXX618G
Email Address	THANNI73@GMAIL.COM
Mobile Phone No	(Phone) +65-96407549
Alternative Phone No	+65-96407549

### VEHICLE PARTICULARS

Manufacturer	BMW
Model	216i
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car

### INSURANCE COMPANY

Name of Insurance Company	Direct Asia
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	MT/00825181
Cover Note Number	-

### DRIVER

Name of Driver	THANAPORN LORCHIRACHOONKUL
NRIC No	SXXXX618G
Date Of Birth	10/09/1973
Occupation	Indoor



Of Driving Pass .....  
ing experience .....  
ender .....  
Mobile Number .....  
Alt. Phone Number .....  
Email Address .....  
Address .....  
Address complement .....  
Postcode .....  
Is the driver the policyholder? .....  
If No, Relationship of the Driver with the Insured .....  
Does Driver Own Other Vehicles? .....  
Vehicle Registration Number of Other Vehicle Owned by Driver .....  
Insurance Company of Other Vehicle Owned by Driver .....

29/05/2003  
17 YEARS AND 9 MONTHS  
Female  
(Phone) +65-96407549  
+65-96407549  
THANNI73@GMAIL.COM  
59 HILLVIEW AVENUE #04-05  
-  
669616  
Yes  
-  
No  
-  
-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident .....  
Weather Conditions .....  
Road Surface .....

Collision - Head to Rear  
Clear  
Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? .....  
Number of vehicles involved in the accident .....  
Was anybody injured in the Accident? .....  
Was any injured conveyed to hospital by ambulance? .....  
Was any other material or property damaged? .....  
Number of Passengers (Including Driver) .....  
Has the driver been approached by unknown person(s)  
soliciting/offering accident claims assistance? .....

No  
2  
No  
-  
Yes  
2  
No

#### PASSENGER 1

Name .....  
Gender .....

CHIN YAAN LI  
Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? .....  
Was notice of intended Prosecution given? .....  
If yes, against whom? .....

No  
No  
-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO SKETCH PLAN

#### ATTACHMENT(S)

Are accident photos available for attachment? .....  
Was there any video captured by Car Camera? .....  
Was there any audio recorded? .....

Yes  
Yes  
Yes

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number .....  
Vehicle Manufacturer .....  
Vehicle Model .....  
Vehicle Variant .....  
Vehicle Colour .....  
Vehicle Category .....  
Name of Driver .....  
NRIC No .....

SKZ3180B  
Honda  
-  
-  
-  
Private car  
CHUA CHER PENG  
SXXXX148Z

Contact Number .....  
Address .....  
Address complement .....  
Postcode .....  
Insurance Company Name .....  
Nature Of Damage .....  
Details of property damaged in accident .....  
No. Of Passenger (Including Driver) .....

(Phone) +65-96834445  
-  
-  
-  
-  
-  
-

SLN L&A

Veh No:



## SKETCH PLAN

### IMPORTANT NOTICE

VEHICLE NO: STA 1930 H  
ACCIDENT DATE: 01/09/2019 06:50

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

**NOTE: DO NOT THAT YOU MAY HAVE A 14-DAYS TIMEFRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE REFER TO YOUR POLICY FOR MORE INFORMATION.**

Policyholder's Signature

Date & Time: 8/2/21

12:55

Driver's Signature

(If driver is not the policyholder)

Date & Time:


CHARN'S CUSTOMCRAFT

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

# SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 8/2/2021 at about 0650 I was driving my car SK11930H along Clement Road. The car in front slowed down significantly to near stop. I followed and slowed down as well. The car SK13180B hit me from behind.

No person was injured.

OWN DAMAGE ( ) 3RD PARTY CLAIM (✓) REPORTING ONLY ( ) OWN WORKSHOP (✓)

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time: 08/02/2021

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

CHARN'S CUSTOMCRAFT  
Reporting Centre Person's Signature  
Name:  
NRIL/IN No:



Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	618G
Vehicle No.:	SFA1930H
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Apr 2021
Vehicle Make:	B.M.W.
Vehicle Model:	216I GRAN TOURER NAV
Primary Colour:	Grey
Manufacturing Year:	2019
Engine No.:	33555697B38A15A
Chassis No.:	WBA6V120905N54314
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$34,328.00
Original Registration Date:	14 Aug 2019
First Registration Date:	14 Aug 2019
Transfer Count:	0
Actual ARF Paid:	\$40,060.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Aug 2029
PARF Rebate Amount:	\$30,045.00
COE Expiry Date:	13 Aug 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,725.00
COE Rebate Amount:	\$27,200.00
Total Rebate Amount:	\$57,245.00

The information contained herein is correct as at 21 Apr 2021

OK



SEARCH

Price Range

Depreciation

2019

Vehicle Type

Search

View All

Advanced Search

Home » Used Cars » GOwheeler Pte Ltd » BMW 2 Series 216i Gran Tourer

## BMW 2 Series 216i Gran Tourer

Overview

Financial

Accessories

Similar

Research

Photos

Map

PREMIUM AD



Our Accreditations



Price **\$112,800**

Depreciation ⓘ **\$11,820 /yr**  
View models with similar depre

Reg Date **30-Sep-2019**  
(8yrs 5mths 8days COE left)

Mileage **46,968 km (30.1k /yr)**

Manufactured ⓘ **2019**

Road Tax ⓘ **\$684 /yr**

Transmission **Auto**

Dereg Value ⓘ **\$46,251 as of today (change)**

OMV ⓘ **\$24,215**

COE ⓘ **\$31,759**

ARF ⓘ **\$25,901**

Engine Cap **1,499 cc**

Power **80.0 kW (107 bhp)**

Curb Weight ⓘ **1,490 kg**

No. of Owners ⓘ **1**

Type of Vehicle **MPV**

### Features

109Bhp TwinPower Turbocharged Engine, 190Nm Torque, 7 Speed DCT Gearbox, 0 To 100Km/H In 11.7s, Bluetooth, Keyless Start/Stop, Reverse Sensors. View specs of the BMW 2 Series Gran Tourer (2018)

### Accessories

16" Rims, Auto Rain Sensors, Steering Wheel Controls, Knockdown Rear Seats, ISOFIX.

### Description

Low Interest Rate. Maintained And Warranty By BIS Automobiles Valid Till 29 Sep 2022. Free Servicing Valid Till 29 Sep 2022. 7-Seater Gran Tourer With Up To 1,905 Litres Of Cargo Space. Balloon Scheme And In-House Financing Options Available. Buy With A Peace Of Mind. 1 Owner. 100% Genuine Mileage. Well Maintained. Immaculate Condition. All Trade In Welcome.

### Category

PARF Car, Premium Ad Car

### Status

Available for sale. Shortlist this car to get alerted whenever the price or availability changes.

### Resources



SHORTLISTED

HISTORY


enCarMart Used Car Warranty

r repair bill. Ask your dealer for a warranty on this car. Learn more

Compare



### Price Chart



Click on the point to view the vehicle



Shortlist



Compare



Report Error



More

### Seller Information

GOwheeler Pte Ltd