AUTOMOBILE HUB ENTERPRISE

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY@KAKI BUKIT SINGAPORE 417883 TEL: 65096584

TO

: AXA

DATE : 8/2/2021

ATTENTION

: MOTOR INSURANCE CLAIM

JOB TYPE : T/P CLAIM

ESTIMATE REPORT

VEHICLE DETAILS

Veron.

VEHICLE NO

: SJR358E

VEHICLE MODEL

: TOYOTA ALLION

CHASSIS NO

: NZT2603037475

ACCIDENT DETAILS

DATE

TIME

THIRD PARTY REQUESTOR / CONTACT

SIONG / 97864483

CLAIM DETAILS: PARTS

CLAIM DETAILS: PARTS	QTY	UN	IT PRICE	TOTAL
IŢEMS	1	Ś	968.40	\$ 968.40
1 REAR BUMPER Store	1	\$	68.00	\$ 68.00
2 REAR BUMPER SIDE HOLDER LH	1	\$	85.60	\$ 85.60
3 REAR BUMPER REFLECTOR LH	1	\$	103.70	\$ 103.70
4 REAR BUMPER IMPACT BRACKET ET	1	\$	584.60	\$ 584.60
5 REAR END PANEL	1	\$	368.00	\$ 368.00
6 TAILLAMP LH Cruberd	TOTAL DOLCE.			\$ 2.178.30

1490

TOTAL PRICE:

2,178.30

LESS 25% SUB TOTAL PRICE:

544.57 1,633.73

SPECIAL NETT ITEMS

SPECIAL NETT ITEMS	QTY	UNITE	PRICE	TOTAL
ITEMS	1 SET	\$	50.00	\$ 50.00
1 REAR BUMPER CLIPS THE METAL STATE OF THE PARTY OF THE P	1 SET	\$	280.00	\$ 280.00
2 REVERSE SENSOR	1 SET	Ś	60.00	\$ 60.00
3 REAR END PANEL SEALANT ALL		TOTAL:		\$ 390.00

ABOUR	PRICE	ADJUSTED COST	APPROVED
JOB			
1 PANEL BEATING, REMOVE AND REFIT PARTS	\$ _600.00	300	
1 PANEL BEATING, REMOVE AND RET	\$ 600.00	400	
2 SPRAY PAINTING TO AFFECTED AREA	\$ 50.00	- 30	
3 WIRING CHECK	\$ 100.00	-60	
4 TUFF COAT	\$ -100.00	-50	
5 TO REMOVE REVERSE SENSOR	\$ -100.00	20	

6 TO REMOVE AND REFIT UPHOLSTERY 100.00 TOTAL: \$ 1,550.00 **ESTIMATE REPORT** \$ 2,023.73 TOTAL PARTS COST: total: 2337.50 1/s: 18k. 03Days \$ 1,550.00 TOTAL LABOUR COST: \$ TOTAL REPAIR COST: 3,573.73 4173.73 **APPROVED DETAILS** SURVEYOR: FAX: CONTACT:

PART BY PART / LUMP SUM: NO. OF DAYS:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: