

HUI HUANG HONG BAO MOTORS

2 Kaki Bukit Ave 2 #02-11 Kaki Bukit AutoHub Singapore 417921

Tel : 6844 7414 Fax : 6844 7401 Email : alisonhbb@gmail.com

M/s Popular Rent A Car Pte Ltd
501 Guillemard Road
Singapore 399840

Date of survey: 16 February 21

Motor surveyor: LKK Auto

Surveyor: Adrian Ling

8th February 2021

Type of repair: Lump Sum

Estimate cost of repairs to Honda Shuttle Hybrid - SLR 5769 X

1 pc	Tailgate	\$ 1,193.40	it
1 pc	Tailgate 'H' emblem	\$ 33.10	ney
1 pc	Tailgate 'Hybrid' emblem	\$ 65.20	ney
1 pc	Tailgate 'Shuttle' emblem	\$ 55.00	ney
1 pc	Tailgate weatherstrip	\$ 95.10	cut
1 pc	Tailgate inner lock	\$ 175.10	?
1 pc	Tailgate inner trim board	\$ 619.50	X
1 pc	Rear windscreen lower moulding	\$ 80.00	ney
1 pc	Rear windscreen top moulding	\$ 30.10	ney
1 pc	Rear end panel	\$ 601.50	Rx photo
1 pc	Rear end panel centre garnish	\$ 155.60	?
1 pc	Rear bumper	\$ 1,150.60	de
2 pcs	Rear bumper retainers @S\$28.60	\$ 57.20	?
		\$ 4,311.40	
	Less 20%	\$ 862.28	
		\$ 3,449.12	
1 set	Tailgate inner trim clips	\$ 20.00	SN X
1 set	Rear bumper clips	\$ 25.00	SN ney
1 pc	Rear windscreen sealant	\$ 40.00	SN ney
1 set	Reverse sensors	\$ 250.00	SN 200mm
		\$ 150.00	120.
	To remove and refit rear windscreen glass	\$ 60.00	30.
	To remove and refit reverse sensors	\$ 120.00	60.
	To remove and refit tailgate interior fittings	\$ 50.00	30.
	To remove and refit back-up camera	\$ 1,200.00	600
	Labour charges to remove, adjust and renew the above parts etc	\$ 60.00	30.
	Tuff kote	\$ 50.00	30.
	Wiring charges	\$ 1,200.00	700
	Spray painting	\$ 6,674.12	

Dollars : Six thousand six hundred seventy-four dollars and twelve cents.

Tan Jiah 97495749 / 62563561
WP 16/2/21 @ 520pm
4/5 Resurvey after repair.
Tan Jiah @ Khabbo.com
05 days

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.



2. This Form must be completed by the Policyholder and/or the Authorised Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	08/02/2021 16:26 (SGT)
Date of Accident	07/02/2021 16:20 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	CTE TOWARDS TOWN
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLR5769X

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	POPULAR RENT A CAR PTE LTD
Company Reg No	1XXXXX195Z
Email Address	INFO@POPULARCAR.COM
Mobile Phone No	(Phone) +65-67428888
Alternative Phone No	(Home) +65-67428888

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Shuttle
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire

INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	999994047
Cover Note Number	-

DRIVER

Name of Driver	EDMOND D CHAN
NRIC No	SXXXX205E
Date Of Birth	23/02/1981
Occupation	Outdoor

Contact Number	(Phone) +65-91717121
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHD3005B
Vehicle Manufacturer	Hyundai
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	CHARLES PANG ENG HIN
NRIC No	SXXXX419D
Contact Number	(Phone) +65-92973700
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SKD8886K
Vehicle Manufacturer	Lexus
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	LIN KAILI
NRIC No	SXXXX784H
Contact Number	(Phone) +65-86924672
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

WITNESS DETAILS

WITNESS 1

Name	REUBEN
Phone	(Phone) +65-90670790
Email	-

Edmond Ch

Edmond Ch

Describe Circumstances of the Accident

THERE WAS ROAD WORKS ON LANE 1 AT CTE (TOWARDS TOWN)
 SOME CARS CUT INTO LANE 2, CAUSING MULTIPLE BRAKING. ~~THE~~ BRAKING
~~THE~~ I HAD BRAKED IN TIME AND DID NOT HIT THE CAR IN FRONT.
 AS I STARTED MOVING OFF WHEN I HEARD A RING AND 1 SECOND LATER
 WAS HIT BY THE CAR BEHIND ME.
 NO ONE WAS INJURED AT THE TIME.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature
 Time

Edmond Ch

08/02/2021
 11:55 AM

Driver's Signature (if driver is not the policyholder) / Date
 & Time

[Signature]

Witnessed by Reporting Centre
 Personnel

Date Of Driving Pass	29/05/2007
Driving experience	13 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-88788630
Alt. Phone Number	-
Email Address	EDMONDDCHAN@GMAIL.COM
Address	150 MARIAM WAY #04-03 S 507079
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	4
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	UNKNOWN
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO THE ATTACHED.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDA2238R
Vehicle Manufacturer	Toyota
Vehicle Model	Vios
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	LIM XIANG YUN
NRIC No	SXXXX560C