



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC21002032/Qqd3e2	
			Date: 16/04/2021	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 7793T	Veh. Inspected	GBJ 8807K	
Policy No.	Z20VC05006231	Coverage (\$)	0.00	
Claim No.	20/21/21/VC05/024190	Excess (\$)	0.00	
Assign From	KENNY LIM	Assign Date	10/02/2021	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV200 DX	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	VM20133330	Colour	WHITE	
Odometer	20955 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	165/80 R14	TOYO	6 mm	
L/H Front Tyre	165/80 R14	TOYO	6 mm	
R/H Rear Tyre	165/80 R14	TOYO	6 mm	
L/H Rear Tyre	165/80 R14	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/01/2021	Inspection Date	17/02/2021	
Survey held at	HING LEE MOTOR CAR REPAIR & WELDER WORKS BLK 7 UNIT 397-D WOODLANDS RD YEW TEE INDUSTRIAL ESTATE SINGAPORE 677996			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	