

ANNEX

REPAIR DETAILS (XD 4475 G)

Recommended Parts

No	Qty	Particulars	Condition	Repairer's Amount	Adjuster's Amount
1	1	Headlamp Assembly - N/s	Casing Broken	971.00	971.00
2	1	Front Side & Signal Lamp - N/s	Cracked/Broken	674.00	674.00
3	1	Headlamp Top Garnish - N/s	Grazed - To Re-paint	1,120.00	0.00
4	1	Front Side Bumper - N/s	Dented/Cracked	1,719.00	1,719.00
5	1	2 nd Step Board - N/s	Grazed - To Re-paint	2,025.00	0.00
6	1	2 nd Step Board Garnish - N/s	Holder Broken	1,184.00	1,184.00
7	1	2 nd Step Board Garnish Reflector - N/s	Grazed	32.00	32.00
8	1	1 st Step Plate Panel - N/s	Cracked/Broken	356.00	356.00
9	1	Front Wheel Front Mudguard - N/s	Grazed - To Re-paint	679.70	0.00
Sub-Total				8,760.70	4,936.00
Less 0%				0.00	0.00
Total Parts (S\$)				8,760.70	4,936.00

Recommended Labours

No	Particulars	Repairer's Amount	Adjuster's Amount
1	To repair left headlamp top garnish, left 2 nd step board and left front wheel front mudguard including replacement of the left front accident damaged parts.	900.00	600.00
2	To check front lightings and electrical wiring system include focusing both headlights and adjust if necessary.	80.00	50.00
3	To putty and re-spray painting on left headlamp top garnish, left front side bumper, left 2 nd step board, left 2 nd step board garnish and left front wheel front mudguard.	1,155.00	1,050.00
Total Labour (S\$)		2,135.00	1,700.00
Total Repair Cost (S\$)		10,895.70	6,636.00

Adjusted Repair Cost (Part by Part basis)

S\$6,636.00



Our Ref: 20/0058/TP
Vehicle No: XD 4475 G

Allied
Auto Appraisal















Our Ref: 20/0058/TP
Vehicle No: XD 4475 G

Allied
Auto Appraisal









Our Ref: 20/0058/TP
Vehicle No: XD 4475 G

Allied
Auto Appraisal
















RESURVEY (26/11/2020)

















Our Ref: 20/0058/TP
Vehicle No: XD 4475 G

Allied
Auto Appraisal







Our Ref: 20/0058/TP
Vehicle No: XD 4475 G

Allied
Auto Appraisal



BEFORE PAINT (27/11/2020)





Our Ref: 20/0058/TP
Vehicle No: XD 4475 G

Allied
Auto Appraisal



AFTER REPAIR (30/11/2020)





Our Ref: 20/0058/TP
Vehicle No: XD 4475 G

Allied
Auto Appraisal



Our Ref: 20/0058/TP
Vehicle No: XD 4475 G

Allied
Auto Appraisal

