

7203252

REF:

General Instruction:

ASSIGNMENT (Office)

10/02/2021

From (Person): ong lili

of

UPC

Date/Time:

Estimated Cost:

Bill to:

OD/PT/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

FBN 7647R

Insured:

SKF 17060

at Workshop m/s

GP motorway

Tel:

90 B 809

of

282 Macpherson Rd

Policy No:

Claim No:

19/20/20/VP05/023074

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A.

06/2/20

CA / REV / REP. / REV 24 HRS

~PRS.

H.O.D. Endorsement:

Date/Time:

12/2/2020 11:07a

Person Contacted:

Ken Spin

Vehicle IN/OUT[illegible]

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Tuesday, 11 February 2020 6:02 PM
To: alfred_ng@juseq.com.sg; assignments@lkkauto.com; Nivitha (LKK Auto)
Cc: MT_Claim_SG
Subject: RE: ACCIDENT INVOLVING FBN7647R AND SKF1706D ON 6 FEBRUARY 2020 Our ref: 19/20/20/VP05/023024 [External General]
Attachments: 200169.pdf

Lonpac External - General

Without Prejudice
Save as to Costs


Dear Alfred

We are not agreeable with your proposed list of surveyors and we shall appoint LKK Auto Consultants Pte Ltd to conduct the survey.

Dear Nivitha

FYA

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse
Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: alfred_ng@juseq.com.sg [mailto:alfred_ng@juseq.com.sg]
Sent: Tuesday, 11 February 2020 5:45 PM
To: ONG LI LI <llong@lonpac.com>
Subject: ACCIDENT INVOLVING FBN7647R AND SKF1706D ON 6 FEBRUARY 2020

Your ref: 19/20/20/VP05/023024
Our ref: JEQ/200169/0220/GP/PI

Dear Li li,

We refer to your email today.

We are instructed that our client is not agreeable to all the surveyors proposed by you.

Pursuant to Appendix C, pre-action protocol for NIMA cases, we are also instructed to furnish you our client's list of motor surveyors for your selection:-

Vel: in
T: 12126@1107an
C: Ken Sim
E: X
GB

1. Absolute Appraisal Services Pte Ltd;
2. Sincere Appraisal Services;
3. Mc Coy Appraiser Pte Ltd;
4. Delta V Consultant;
5. Prominent Appraiser Pte Ltd;
6. Advance Automotive Consultancy Pte Ltd;
7. Pal's Appraiser Pte Ltd;
8. S K Auto Consultants;
9. Prudent Adjustors Services;
10. CL Appraiser Pte Ltd;

Please be informed that if the above mentioned surveyors is not agreeable by you, our clients' motor vehicle is available for pre-repair inspection at the under-stated workshop;-

GP Motoring Pte Ltd
282 Macpherson Road
Singapore 348607
Mobile :9061-8091
Fax: 6909-9284
Contact person: Mr. Ken Sim

With Regards

Alfred Ng
Executive
Legal Division
On behalf of Mr. Michael Yap
M/s JusEquity Law Corporation
No. 133 New Bridge Road
Chinatown Point
#10-03 Singapore 059413
Tel : 6536 9339
Fax: 6536 5368

IMPORTANT NOTICE:

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

LONPAC INSURANCE BHD

Ref: CS3/LPC20002428/Gyf3e2

300 BEACH ROAD

Date: 19-02-2020

#17-04/07 THE CONCOURSESINGAPORE 199555



Code: LPC2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SKF 1706D	Veh. Inspected	FBN 7647R
Policy No.		Coverage (\$)	0.00
Claim No.	19/20/20/VP05/023024	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	11/02/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA FS150F	c.c	149
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	PMKKC27A0KB204852	Colour	ORANGE
Odometer	24180 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	90/80-17	IRC	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	120/70-17	IRC	5 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.	
--	--

5. General Information

Accident Date	06/02/2020	Inspect Date / Time	12/02/2020 (12:00 PM)
Survey held at	GP MOTORING PTE LTD 282 MACPHERSON ROAD SINGAPORE 348607		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

Report Ref No. CS3/LPC20002428/Gyf3e2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.