

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE I	PTE LTD		Ref:	CS3/ASM21002081/Gvf3e2	
	8 SHENTON WAY TOWERSINGAPOR	!	Date:	25/02/2021		
	ATTN : JOHNNY Y	ONG	(Code:	ASM	
1.	. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SLM 411L	Veh. Inspected		SLQ 9111Y	
	Policy No.	GA490491/1	Coverage (\$)		0.00	
	Claim No.	S1M032FD	Excess (\$)		0.00	
	Assign From	JOHNNY YONG	Assign Date		09/02/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA ALTIS	c.c		1598	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	MR053REH104540929	Colour		WHITE	
	Odometer	177769 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/55 R16	YOKOHAMA		6 mm	
	L/H Front Tyre	205/55 R16	YOKOHAMA		6 mm	
	R/H Rear Tyre	205/55 R16	YOKOHAMA		6 mm	
	L/H Rear Tyre	205/55 R16	YOKOHAMA		6 mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.					
5.	5. General Information					
	Accident Date	07/02/2021	Inspect Date / T	ime	18/02/2021 (03:00 PM)	
	Survey held at	JEMENTAH MOTOR WORKS				
	BLK 14 DEFU LANE 10 #01-406 SINGAPORE 539195					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days					

Report Ref No. CS3/ASM21002081/Gvf3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor