

ASS. REC. BY:

REF: CS3/ASM21002081/Gvf3

Special Instruction:

Surveyor: GQ ASSIGNMENT (Office)From (Person): JHONNY YONG of AXA Date/Time: 9/2/2021 2:36 PM

Estimated Cost: _____ Bill to: _____

OD ☒ TP WS/ TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLQ 9111Y Insured: SLM 411Lat Workshop m/s Jementah Motor Works Tel: 9299-6636of Blk 14 Defu Lane 10 #01-406Policy No: _____ Claim No: S1M032FD

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 07-02-2021
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP" H.O.D. Endorsement: _____

Date/Time: 15-02-21 10.23A.M Person Contacted: CHUAN Vehicle IN ☒ OUT

Date/Time	Action/Instruction (☒) Estimate
	SLQ 9111Y- ☒
	SLM 411L - ☒
19/2/21	Send IA via Smart Claim
19/2/21	Submit PRS, repair range \$3,000-\$4,000