


62  
PMS

AXA  
ASSIGNMENT

From \_\_\_\_\_ Date \_\_\_\_\_  
Estimated Cost \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No. \_\_\_\_\_  
at Workshop m/s Jementah  
of \_\_\_\_\_  
Insured \_\_\_\_\_  
Policy No \_\_\_\_\_  
Claims No \_\_\_\_\_  
Sum Insured \_\_\_\_\_ Excess \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: \$52k  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: 5 days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No 6029111 at Page 28 Dec 2015  
Type M.Cycle / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_  
Make: Toyota Altis CC 1598  
Colour: white A/C: Insured / Std / NI / NA  
Sp Reading 177769 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: MR053REH104540929  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brake: In order / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD / R/Rim or  
Tyre Size: F: 205/55R16  
R: 11  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or \_\_\_\_\_  
Front \_\_\_\_\_ Rear \_\_\_\_\_  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. 7/2/21 D.O.I. 18-02-21  
Survey held at W/S 3 pm  
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time \_\_\_\_\_ Action / Instruction \_\_\_\_\_

CB: 38853  
\$3000 - \$4000

Date/Time, File Pass to?

☐ : Prell. Report  
☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation

\_\_\_\_\_ + RS \_\_\_\_\_

Flashes

\_\_\_\_\_

Date/Time, File Return to?

19/2/21-Typist

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech Insp (\$

☐ Photo (\$

PRR

PRR