

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE I	PTE LTD		Ref:	CC4/ASM21002104/Ups3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	15/04/2021	
	ATTN:RICHARD A	NG		Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHA 7978H	Veh. Inspected	l	SMJ 7976G	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S1M0359E	Excess (\$)		0.00	
	Assign From		Assign Date		15/02/2021	
2. Vehicle Particulars & Condition						
	Make & Model	MERCEDES BENZ E200 (A)	c.c		1991	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	WDD2130422A540896	Colour		GREY	
	Odometer	34515 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/55 R17	PIRELLI		7 mm	
	L/H Front Tyre	225/55 R17	PIRELLI		7 mm	
	R/H Rear Tyre	225/55 R17	PIRELLI		7 mm	
	L/H Rear Tyre	225/55 R17	PIRELLI		7 mm	
4.	. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	12/02/2021	Inspection Dat	е	15/02/2021	
	Survey held at	FASTECH AUTO PTE LTD	•			
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883				
5a.	n. Remarks					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	STIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				
	Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. Estimate Days of Repair					