

## COMFORTDELGRO ENGINEERING PTE LTD

**REPAIR ESTIMATE\***

VEHICLE NO SHA1313R

DATE 15.02.21

MAKE :

CHIANG/AIG

MODEL I-40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER			\$1,052.20 <i>Rs</i>
1	RADIATOR GRILLE			\$1,480.00 <i>an</i>
1	RADIATOR EMBLEM			\$45.90 <i>an</i>
10	BUMPER CLIP			\$22.00 <i>an</i>
1	FRONT BUMPER BRACKET TOP LH/			\$44.80 <i>x</i>
1	FRONT BUMPER BRACKET SIDE /LH			\$28.60 <i>x</i>
	<b>SUB TOTAL</b>			<b>\$2,673.50</b>
	<b>20.00%</b>			<b>\$534.70</b>
				<b>\$2,138.80</b>
1	FRONT NUMBER PLATE W/HOLDER			\$55.00 <i>an</i>
	<b>Labour Charge</b>			<b>\$55.00</b>
	Panel Beating		280	\$600.00
	Spray painting		250	\$300.00
	tuff coat		<i>x</i>	\$50.00
	Check Lighting		<i>x</i>	\$50.00
	<b>TOTAL LABOUR</b>			<b>\$1,000.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$3,193.80</b>
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanpin 97495749  
 WP 15/2/20 @ 3pm  
 L/S Resurvey after repair  
 2 days  
 tanpin@phanta.com

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 15.02.2021 13:44

Page : 1

Team: ARC Repair TP(CLS0)1

**JOB CARD**

Sales Order:

JC NO.305453417

CUSTOMER

VMS COMFORT TRANSPORTATION PTE LTD  
CUSTOMER NO. 7010045  
ADDRESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
L (R) 65508755 (O)  
(P)


SCOUT CARD NO.

REGN NO.: <b>SHA1313R</b>	MILEAGE
MAKE: <b>HYUNDAI</b>	FUEL E.....1/2.....F
MODEL <b>I-40</b>	DATE/TIME IN <b>15.02.2021 09:55</b>
YR OF MANU. <b>12.05.2016</b>	TARGET DATE
CHASSIS CODE <b>KMHLB41UMGU090095</b>	COMPLETION DATE/TIME:

JOB DESCRIPTION

Ident Date: 15.02.2021  
NATURE: 3P 15.02.2021

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: **SHA1313R** **CHIANG**

Vehicle No.: **SHA1313R**

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard