

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA1313R

DATE 15.02.21

MAKE :

CHIANG/AIG

MODEL I-40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
1	FRONT BUMPER COVER			\$1,052.20	XX DE ✓
1	RADIATOR GRILLE			\$1,480.00	an
1	RADIATOR EMBLEM			\$45.90	an
10	BUMPER CLIP			\$22.00	an
1	FRONT BUMPER BRACKET TOP LH/			\$44.80	X NN
1	FRONT BUMPER BRACKET SIDE /LH			\$28.60	X NN
	SUB TOTAL		2600.10	\$2,673.50	
	20.00%		2080.08	\$534.70	
				\$2,138.80	
1	FRONT NUMBER PLATE W/HOLDER		55	\$55.00	an
	Labour Charge			\$55.00	
	Panel Beating		280	\$600.00	
	Spray painting		250	\$300.00	
	tuff coat		X	\$50.00	NN
	Check Lighting		X	\$50.00	NN
	TOTAL LABOUR		530	\$1,000.00	
			2665.08		
			LS\$2100		
	ESTIMATE TOTAL		2 DAYS #	\$3,193.80	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

Tanpin 97495749
 WP 15/2/20 @ 3pm
 L/S Resurvey after repair
 2 days
 tanpin@phanta.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 15.02.2021 13:44

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD

Sales Order:

JC NO.305453417

CUSTOMER

VMS COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO. 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
L (R) 65508755 (O)
(P)

SCOUT CARD NO.

REGN NO.: SHA1313R	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 15.02.2021 09:55
YR OF MANU. 12.05.2016	TARGET DATE
CHASSIS CODE KMHLB41UMGU090095	COMPLETION DATE/TIME:


JOB DESCRIPTION

Ident Date: 15.02.2021
NATURE: 3P 15.02.2021

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: **SHA1313R** **CHIANG**

Vehicle No.: **SHA1313R**

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard