

ASS. REC. BY:

REF:

AIG/ 21002137/K9

Kenneth

ASSIGNMENT

Pmx 706S

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

Lim Motor

of

Insured:

Policy No.

21000504589

Claims No.

296204647756

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

10/14

days

Res.: Yes or No

Lum Sum:

1.3.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 PR1 10-12K

11/03/21 Submit DAR. (Simon do DAR)

Veh No:

SMA 1366C

Yr Regn:

12, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Ponto

Wagon

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

4616

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

M141-228143-100068887

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

9

mm

Rear

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

7/2/21

D.O.I.

16/2/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

2/15

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1) 11/3 11/3/21

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

14

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

MEK DAR

Lump Sum / I.B.I. (\$



**SINGAPORE
POLICE FORCE**



T/20210208/7017

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 4
Report No: T/20210208/7017

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 08/02/2021 13:05		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: LOH HONG MENG			Address: 156 BEDOK SOUTH AVENUE 3 #04-599 SINGAPORE 460156		
ID Type / ID No.: NRIC NO / S1580694Z			Contact No.: Home/Office: Mobile: 96498198		
Nationality: SINGAPORE CITIZEN			Email: charley_loh@yahoo.com.sg		
Sex: Male	Age: 57	Date of Birth: 13/09/1963	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Grah driver			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 07/02/2021 13:20	Type of Location: Straight Road
Location: CENTRAL EXPRESSWAY				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of
SKX3162Z	Car					0
SLM1386C	Car					0
SMX706S	Car	TOYOTA	SIENTA STANDARD (AUTO)	Brown	Seriously Damaged	3



**SINGAPORE
POLICE FORCE**



T/20210208/7017

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No. 65470000

2 of 4

Report No. T/20210208/7017

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMX706S	NTUC Income Insurance Co-Operative Limited	5120424974	08/01/2021	07/01/2022

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA		
Driver				
Name	BENJAMIN TAN CHENG WEI		ID No.	S9503679A
Related Vehicle	SKX3462Z (Car)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL		Date	NIL
No. of Days granted Medical Leave	NIL		Degree of	NIL
Driver				
Name	HENG HANN JEN		ID No.	S2164543D
Related Vehicle	SLM1366C (Car)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL		Date	NIL
No. of Days granted Medical Leave	NIL		Degree of	NIL
Driver				
Name	LOH HONG MENG		ID No.	S158C691Z
Related Vehicle	SMX706S (Car)		Contact No.	96498198
Hospital/Clinic	NIL		Class of Driving Licence & Expiry	Class: 3 Date of Expiry: NIL
Date	NIL		Date	NIL
No. of Days granted Medical Leave	NIL		Degree of	Serious



**SINGAPORE
POLICE FORCE**



T/20210208/7017

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 4

Report No: T/20210208/7017

CONTINUATION OF REPORT

Brief Details:

On 7 February 2021, I was driving my vehicle, SMX 760S on the second lane from the right. Suddenly, the driver of vehicle SKX 3462Z, cut in my lane from the lane to my left. I could not break in time and collided into the rear of SKX 3462Z. Shortly after, a violent impact came from the back and I discovered that SLM 1366C had rear ended my vehicle. My vehicle did not go on to hit the vehicle SKX 3462Z ahead a second time because my right leg is fully on the break paddle.

Damage to the rear of my vehicle is very severe compared to the frontal damage. I am filing this report for compensation purposes. I had three passengers with me at the material time of the accident.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20210208/7017

4 of 4

Report No. T/20210208/7017

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPB /
BOON YEN KIAN
Contact No.: 65476172

Authentication Stamp
NR168

Signature Of Informant:

The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time:
08/02/2021 13:05

Classification Of Case:

(67)Deformed (68)Shifted (69)Buckled (10)Broken (11)Necessary
(12)Missing (13)Torn (14)Unconfined (15)Not Working

MOTORCAR (Rear)

(1)Replace (✓) (2)Repair (✓) (3)Check (✓)
(4)Not Consistent (N/C)

1.8-2

Rear Portion

NAC	INC	Item	CON	ACQ	Qty
1137	993626	Rear Number Plate		?	
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish		?	
1140	993632	Rear Number Plate Lamp	CRA	2	
1141	992958	Rear Bumper	BT		
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side Grp Lamp	CRA		
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	6	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	DIS	2	
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector Gr	BT		
1154	993036	Rear Bumper Pad Protector L/R	BT	2	
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector L+R	CRA	2	
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	SWT		
1159	993327	Rear End Panel	BUC		
1160	993339	Rear End Panel Top Garnish	BT		
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	CRA		
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel	DD R		
1166	995116	Rear RH Taillamp	CRA		
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel	DD R		
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	BUC		
1182	991328	Tailgate Emblem	NEC	2	
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding	CRA		
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp	CRA	2	
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant	NEC		
1197	994629	Tailgate Lock	JM		
1198	994651	Tailgate Rubber	BT		
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board	CRA		

Vehicle No:

SMX7065

NAC	INC	Item	CON	ACQ	Qty
1202	993784	Spare Tyre Board		?	
1203	994328	Spare Tyre Panel	BUC		
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw		?	
1206	993787	Spare Tyre Cover		?	
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim		?	
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim	CRA		
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille		?	
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			
		Lock Holder		PP	

No of Items: _____ Assessor: _____

MOTOR CAR (Frt)

202

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	DD	/	
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish	DIS	/	
1004	991300	Frt Bumper	DD	/	
1005	992341	Frt Bumper Clips	NEC	/	6
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	AS	/	2
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector	LH + RH	DIS	2
1012	991420	Frt Bumper Pad Emblem	NEC	/	
1013	991363	Frt Bumper Grille	CRA	/	
1014	991301	Frt Bumper Moulding	CRA	/	
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover		?	
1018	991355	Frt RH Bumper Fog Lamp Cover		?	
1019	995079	Frt LH Bumper Fog Lamp		?	
1020	995080	Frt RH Bumper Fog Lamp		?	
1021	991793	Frt Grille	CRT	/	
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	BT R	/	
1026	992025	Frt Support Panel Top Garnish Cover		?	
1027	992416	Horn			
1028	991277	Frt Brace Panel		?	
1029	995153	Frt LH Headlamp Assy		?	
1030	991821	Frt RH Headlamp Assy		?	
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	DD	/	
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock		?	
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser		?	
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator		?	
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy		?	
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

Vehicle No: SMX 7065

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			?
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			?
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

No of items:

Assessor: