

COMFORTDELGRO ENGINEERING PTE LTD

Date: 15.02.2021

Time: 12:46:14

Page: 1

REPAIR ESTIMATE

NTUC - 45
LKK -

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305453416
REGN NO : SHC8202X
MILEAGE : 0000000000
MAKE : MERCEDES BENZ
MODEL : E220CDI(E6)
DATE OF REGN : 13.05.2015
DATE/TIME IN : 15.02.2021 09:30
ACCIDENT DATE : 09.02.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0202-2058-G	MIRROR ORNAMENTAL COVER RH	1	350.00	20.00	280.00	am	
0002	04-01-0202-2100-G	MIRROR GLASS FRT RH	1	380.00	20.00	304.00	am	
0003	04-01-0202-0898-G	MIRROR W/SIGNAL LAMP FRT RH	1	890.00	20.00	712.00	am	1620
0004	04-01-0202-2099-G	MIRROR MOTOR FRT RH	1	920.00	20.00	736.00	am	1296

SUB-TOTAL : 2,032.00

JOB NATURE

0000	PB	PANEL BEATING		450.00		200		
0001	SP	SPRAYPAINT CHARGE		350.00		100		
0002	17-01	CHECK ALL LIGHTING		30.00		330		1626
				SUB-TOTAL :		830.00		450/1300 #

TOTAL : 2,862.00

MVA NAME & SIGNATURE
DATE :

[Signature]

SURVEYOR NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO

Tanjim 9749 5749 Giti
WP' 15/2/21 @ 4pm
4/5 Resurvey after repair
1 day
Tanjim Rikhartharan

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modification shall be allowed
- Supplementary repairs must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: