


Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Trans Cab
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 05 days Res.: Yes or No
 Lum Sum: 1-B.1% 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHF 6656 Yr Regn: 08.20
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toy Puv c.c 1798
 Colour M.P. White / Red AC: Insured / Std / NI / NA
 Sp. Reading 56906 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTDKB3FU903091301
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: NI / S/Rim / STD / RIm or
 Tyre Size: F: Sailun 195/65R15
 R: Run
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 9 mm R/Bal. 6 mm
 L/Bal. 9 mm L/Bal. 6 mm
 D.O.A. 8/2/21 D.O.I. 15/2/2021
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
N/S body
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
/	

Date/Time, File Pass to? : Prell. Report
 : Final Report
 1) _____
 Date/Time, File Return to? _____
 2) _____

Days Of Repair: _____
 Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
 Transporta: _____
 S - RS. SI _____
 Fines _____
 Others _____
 TOTAL _____

Report Format :
 Lump Sum / I.B.I: (\$ _____)

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G

SHF665E

AAD2102-040

*Not Authorized
 Recovery B4 point*

Vehicle No.:
 Chassis No.:
 Vehicle Make: **15 FEB 2021**
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

SHF665E
 JTDKB3FU903091301
 TOYOTA
 PRIUS GEN 4
 08/02/2021
AIG
 14/08/2020

PART	LIST		
1 FENDER SUB-ASSY, FRONT LH	\$ R	977.80	X
1 EMBLEM, SIDE PANEL	\$ R	54.60	✓
1 PANEL SUB-ASSY, FRONT DOOR, LH	\$ B4/wat	1,300.70	✓
1 WEATHERSTRIP, FRONT DOOR, LH	\$ S	231.30	X
1 HINGE ASSY, FRONT DOOR, LOWER LH	\$ R	110.60	X
1 HINGE ASSY, FRONT DOOR, UPPER LH	\$ R	97.50	X
1 TAPE, BLACK OUT, NO.1 FRT LH	\$ R	13.30	—
1 TAPE, BLACK OUT, NO.2 FRT LH	\$ R	43.50	—
1 TAPE, BLACK OUT, NO.3 FRT LH	\$ R	26.30	—
1 MOTOR ASSY, POWER WINDOW REGULATOR, FRT LH	\$ S	926.00	X
1 REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH	\$ S	238.30	X
1 PANEL SUB-ASSY, REAR DOOR, LH	\$ R	1,294.90	X
1 WEATHERSTRIP, REAR DOOR OPENING TRIM, LH	\$ S	293.00	X
1 HINGE ASSY, REAR DOOR, LOWER LH	\$ R	87.10	X
1 HINGE ASSY, REAR DOOR, UPPER LH	\$ R	98.90	X
1 TAPE, BLACK OUT, NO.1 REAR LH	\$ R	21.90	X
1 TAPE, BLACK OUT, NO.2 REAR LH	\$ R	34.90	X
1 TAPE, BLACK OUT, NO.3 REAR LH	\$ R	15.40	X
1 MOTOR ASSY, POWER WINDOW REGULATOR, LH	\$ S	926.00	X
1 REGULATOR SUB-ASSY, REAR DOOR WINDOW, LH	\$ S	206.70	X
1 PANEL SUB-ASSY, QUARTER, LH	\$ R	871.50	X
1 LINER, REAR WHEEL HOUSE, LH	\$ S	139.80	X
1 MOULDING ASSY, BODY ROCKER PANEL, LH	\$ R	594.80	✓
TOTAL	\$	8,604.80	
25%	\$	2,151.20	
	\$	6,453.60	

Trans-cab Auto Services Pte Ltd

AAD2102-040

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF665E

Special Nett

2	FENDER CLIP	\$	<i>Nn</i>	130.00	X
1	FENDER LINER CLIP	\$	<i>Nn</i>	65.00	X
1	FRT BUMPER CLIP	\$	<i>Nn</i>	65.00	X
2SET	DOOR WEATHERSTRIP CLIP	\$	<i>Nn</i>	130.00	X
1	FRT DOOR STICKER TRANSCAB	\$	<i>Nn</i>	100.00	<i>6000</i>
1	TYRE	\$	<i>Sm</i>	350.00	X
1	RIM	\$	<i>Sm</i>	1,879.40	X
1	HUB CAP	\$	<i>Nn</i>	211.50	✓
1SET	CLIP, ROCKER PANEL MOULDING	\$	<i>Nn</i>	65.00	✓
	TOTAL	\$		2,995.90	

TOTAL PARTS \$ 9,449.50

LABOUR

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	<i>600</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,400.00	<i>5000</i>
Putty And Spray Painting Of The Affected Portion.	\$	1,400.00	<i>13200</i>
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	<i>300</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>200</i>
TOTAL	\$	3,590.00	

Over All Total \$ 13,039.50

(PART-BY-PART) Repair Days *20 days*

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 08/02/2021 14:37 (SGT)
Date of Accident 08/02/2021 07:20 (SGT)
Exact Location of Accident Singapore
Additional Location Information ALONG YISHUN RING ROAD NEAR BUS STOP 59579
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHF665E

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner TRANS-CAB SERVICES PTE LTD
Company Reg No 2XXXXX878K
Email Address Claims@transcab.com.sg
Mobile Phone No (Phone) +65-62866666
Alternative Phone No +65-62866666

VEHICLE PARTICULARS

Manufacturer Toyota
Model Prius
Variant -
Exact purpose for which vehicle was being used at time of accident Private hire
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Taxi

INSURANCE COMPANY

Name of Insurance Company Axa
Type of Coverage ThirdParty
Fleet Policy Yes
Policy Number VFX/P2413997
Cover Note Number NA

DRIVER

Name of Driver CHEONG MENG ENG
NRIC No SXXXX535D
Date Of Birth 10/07/1964
Occupation Outdoor

Date Of Driving Pass	25/11/1986
Driving experience	34 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-85230918
Alt. Phone Number	-
Email Address	Claims@transcab.com.sg
Address	HDB Matilda Court, 233A Sumang Lane
Address complement	#02-325
Postcode	821233
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I WAS AT THE MENTIONED LOCATION AT THE RIGHT LANE GOING STRAIGHT WHEN THIRD PARTY MAKE A LANE CHANGE OUT AND CAME INTO MY LANE AND COLLIDED ONTO THE LEFT SIDE OF MY VEHICLE. ONLY TWO VEHICLES WERE INVOLVED WITHOUT ANY INJURIES


ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMU8803H
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	ASHWIN PRAKASH
NRIC No	SXXXX586Z
Contact Number	-
Address	-

SKETCH PLAN



Veh A: SHF66E
Veh B: SM4880M

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHED STATEMENT.

Large rectangular area with horizontal lines for writing the description of the accident circumstances.

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
ANG Q HAO, VICTOR

Reporting Centre Personnel's Signature
Name:
NRC/IN No.:

ACCIDENT STATEMENT (2000 characters)

I WAS AT THE MENTIONED LOCATION AT THE RIGHT LANE GOING STRAIGHT WHEN THIRD PARTY MAKE A LANE CHANGE OUT AND CAME INTO MY LANE AND COLLIDED ONTO THE LEFT SIDE OF MY VEHICLE. ONLY TWO VEHICLES WERE INVOLVED WITHOUT ANY INJURIES.

14 Aug 2021
14 Aug 2021
0
\$18,500.00
Yes
13 Aug 2021
\$10,847.00
13 Aug 2021
A - Car (at 1,500k & YWwy 110km/h)
0
\$20,752.00
\$20,001.00
\$31,494.00

Taxi Voucher No.:

OK

DECLARATION

We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
ANG QI HAO, VICTOR

MARS Officer

Registered Owner or Driver's Signature

Job Complete Date/Time

8 February 2021 at 10:13 AM

Date/Time:

8 February 2021 at 10:13 AM