



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:RICHARD			Ref: CC4/ASM21002179/Ups3q2 Date: 15/04/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4218Y	Veh. Inspected	SFU 6416M	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S1M0359K	Excess (\$)	0.00	
Assign From		Assign Date	16/02/2021	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E200 (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	1996	
Chassis No.	WDB2100352A239400	Colour	BLUE	
Odometer	527411 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R16	MICHELIN	6 mm	
L/H Front Tyre	225/55 R16	MICHELIN	6 mm	
R/H Rear Tyre	225/55 R16	MICHELIN	6 mm	
L/H Rear Tyre	225/55 R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/02/2021	Inspection Date	16/02/2021	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	