

ASS. REC. BY:

REF: CS3/ASM21002180/Qtf3

Special Instruction:

Surveyor: SUN PINASSIGNMENT (Office)From (Person): YU Dominic Yishan of AXA Date/Time: 16 February 2021 11:04 AM

Estimated Cost: _____ Bill to: _____

OD ☒ TP WS/ TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLM 6513L Insured: SHA 88Yat Workshop m/s Aabe Services Tel: 9720 0025of Blk 5035 Ang Mo Kio Ind Park 2 #01-365 Singapore 569538Policy No: _____ Claim No: S1M032ZO

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 12-02-2021
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement: _____

Date/Time: 16-02-2021 1.00P.MPerson Contacted: MR CHUAVehicle IN ☒ OUT

Date/Time	Action/Instruction (☒) Estimate
	SLM 6513L- ☒
	SHA 88Y- NA/INC09012987/w1 DOA :10/06/2009