



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21002183/Utf3q2	
			Date: 19/03/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKM 53Z	Veh. Inspected	GBC 8244X
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2100505/THE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	16/02/2021
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN NV200 (M)	c.c	1461
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	VSKYBAM20U0062171	Colour	GREY
	Odometer	149641 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	175/70 R14	GITI	6 mm
	L/H Front Tyre	175/70 R14	GITI	6 mm
	R/H Rear Tyre	175/70 R14	GITI	6 mm
	L/H Rear Tyre	175/70 R14	GITI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	15/02/2021	Inspection Date	17/02/2021
	Survey held at	RYDER AUTO WORKSHOP LLP 2 Kaki Bukit Ave 2# 02-19 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	