

ASS. REC. BY:

REF: CS/AIG21002192/f3

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Divyashni Subramaniam of AIG Date/Time: 16/2/2021 12:08 PM

Estimated Cost: Bill to:

OD  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SDF 882S Insured: SQ 63D

at Workshop m/s S Three Automotive Recovery Pte Ltd Tel: 6284 1542/6284 1575

of Blk 8 Sin Ming Industrial Estate #01-64/66 Singapore 57564

Policy No: Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 11.02.21  
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP" H.O.D. Endorsement:

Date/Time: 16-02-2021 3.04P.M Person Contacted: YAN ZHEN Vehicle IN  OUT

Date/Time	Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate
	SDF 882S - <input checked="" type="checkbox"/>
	SQ 63D - CC3/AIG12020091/H1k1g2w2 DOA :12/10/2012