SN09212G000G / National Assessment Centre Services [408933] ENTRY DATE & TIME: 16/02/2021 15:45 (SGT) SUBMITTED BY: Chew Hsiao Tong VERSION: 1 (16/02/2021 15:45 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 16/02/2021 15:45 (SGT) Date of Accident 14/02/2021 22:23 (SGT) Exact Location of Accident Opp Goodwill Ct, Singapore Additional Location Information CARPARK Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMT9177F

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner CATHERINE MARY HUGHES MRS CATHERINE MARY LEE NRIC No. SXXXX810D Email Address jonleets@gmail.com Mobile Phone No (Phone) +65-97330197 Alternative Phone No +65-97330197

BMW

VEHICLE PARTICULARS

Manufacturer

Model X4 Variant Exact purpose for which vehicle was being used at time of accident Private use Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Private car

INSURANCE COMPANY

Name of Insurance Company Liberty Insurance Type of Coverage Comprehensive Fleet Policy Policy Number SD20V08519/VPC2/R00 Cover Note Number

DRIVER

Name of Driver LEE TZE SIONG JONATHAN (LI ZHISONG) NRIC No SXXXX399H Date Of Birth 23/02/1986 Occupation Indoor

Date Of Driving Pass 22/11/2005 Driving experience 15 YEARS AND 3 MONTHS Gender Mobile Number (Phone) +65-98155558 Alt. Phone Number Email Address jonleets@gmail.com Address 9 SENNETT AVE Address complement Postcode 467017 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Child Does Driver Own Other Vehicles? Nο Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Hit and run / Vandalism / Damaged whilst parked Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No **DETAILS OF POLICE ACTION** Was the accident reported to the police? Yes Police Station Name Traffic Police Police Station Phone No (Phone) +65-65470000 Alt. Police Station Phone No (Fax) +65-65474900 Police Station Address 10 Ubi Avenue 3 Singapore 408865 Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO POLICE REPORT T/20210216/7019 & STATEMENT. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any audio recorded? No **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number ES9000G Vahiela Manufacturor

Verileie iviarialactarei	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car

Name of Driver Contact Number

Address	 	_
Address complement		_
Postcode		_
Insurance Company Name	 	_
Nature Of Damage		_
Details of property damaged in accident	 	_
No. Of Passenger (Including Driver)		_

SKETCH PLAN

IMPORTANT NOTICE

- Rease report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")


- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the hsurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &

Driver's Signature (if driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel

Sketch Plan



ARRIVED	AT GOODWILL COURT CAPPARE LOT "27" OUTSIDE "TRESH N
	e" at 21:15 on 14 Feb 2021. Parked adjacent to ES 9000G t
the lo	Rt of SMT 91778. No other adjacent lots. Left the vehicle
	until returning at 22:27 on 14 Telo 2021.
1	
Upon r	saturning to vehicle SMT9177E, ES 9000G had deported
Upon a	criving home discovered "G-Sensor" triggered video
capture	
a kno	
SMTOI	776 was unoccupied at the time of impact. Inspection of H
	body revealed a scrath and drigged paint on the
ear	left gossenger door of SMT91776.
A time	delta of less than 40-minutes between the impact those
video	recording and the discovery on the damage to the
	room gastager door. No other impact or liadent
betwee	en these times
1 1	
No all	tempt to communicate by the drive/possenger of ES 9000G.
The	identity of the drier/possenger is unknown to me.
4	
	To the second se

IWe declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time Driver's Signature (I driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



















Police Station Of Origin:

Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

1 of 4

Report No. T/20210216/7019

REPORT OF A TRAFFIC ACCIDENT

	Date/Time Report Made: 6/02/2021 14:17		Vide Report No.:	Station Diary No.:	
Informa	nt's Particu	ulars	ENGLISH OF LABOR DESIGNATION		
Name of Informant: LEE TZE SIONG, JONATHAN			Address: 9 SENNETT AVENUE SINGAPORE 467017		
	Type / ID No.: RIC NO / S8604399H		Contact No.: Home/Office:	Mobile: 98155558	
Nationali BRITISH	1	750	Email: JONLEETS@GMAIL.CO	М	
Sex: Male	Age: 34	Date of Birth: 23/02/1986	Type of Informant: Driver		
Race: Chinese		•	Language: English	Institution / School Name:	
Occupation: Company director			Driving Licence Information Class:	on: Date of Expiry:	

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 14/02/2021 22:20	Type of Location Car Park
Location: Goodwill Cou	rt			
The state of the s		Road Surface:		Road Speed Limit: 20 Km/h
Weather: Clear Traffic Flow: One Way		Road Surface: Dry Traffic Control: Not Controlled		Road Speed Limit: 20 Km/h Traffic Volume: No Traffic

Vehicle No.	Type	Make	Model	Color	Conditio	No of
ES9000G	Car	PORSCHE	SUV	Blue		0
SMT9177E	Car	BMW	X4	Blue	Slightly Damaged	0

Details of Vo	ehicle Insurance	CONTRACTOR OF THE PARTY OF THE	Control Control	5 10 10 10 10 10 10 10 10 10 10 10 10 10
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

Report No. T/20210216/7019

2 of 4

CONTINUATION OF REPORT

Details of Vehicle Insurance					
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date	
SMT9177E	LIBERTY INSURANCE PTE LTD	SDV20V08519/VPC /R00	24/07/2020	23/07/2022	

Details of Perso Any Pedestrian I			ALL DE LA SERVICE	02/15/2	100	
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA			sing: NA
Driver		The state of		GB 122.5	4	
Name	LEE TZE SIONG, JONATHAN		ID No.		S8604399H	
Related Vehicle	SMT9177E (Car)			Contac	t No.	98155558
Hospital/Clinic	NIL			Class of Driving Licence Expiry	e &	Class: NIL Date of Expiry: NIL
Date	NIL Date		Date		NIL	
No. of Days granted Medical Leave NIL			Degree o	of	NIL	

Brief Details.

All events below occurred on 2021-02-14

SMT9177E was parked at Goodwill Court Carpark immediately outside "Fresh N Marine", along the kerb, lot "27". There is only 1 adjacent lot in the immediate vicinity of lot "27".

At 21:15, I parked SMT9177E alongside ES9000G which was parked in the adjacent lot, slightly outside their parking boundary. The left (passenger) side of SMT9177E was parked alongside the right (driver) side of ES9000G. I parked and disembarked the vehicle between 21:15 and 21:17 and proceeded to a nearby TCM shop. In-Car driving video of my arrival/parking captures license plate ES9000G.

I returned to the vehicle SMT9177E at 22:27. The camera's in SMT9177E do not record continuously while parked but are activated by a "G-Sensor".

At 22:23 the "G-Sensor" parking camera was triggered capturing the departure of adjacent car.

I returned to the car at a 22:27 and departed the location. By 22:27 there was no car parked adjacent to SMT9177E. The camera provides a voice alert while I was driving to notify of "events recorded during parking". As I live nearby I returned home before inspecting the car. I found chipped paint and a scratch on the rear left passenger door of SMT9177E.

I was not involved in any other collision and that day SMT9177E was only parked at the above location and at my home (closed, gated carpark). As the car is new I inspect it almost daily for damage or whenever the camera is triggered. I am certain the damage occurred around the times stated above and have strong reason to suspect a driver or passenger of





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 3 of 4 Report No. T/20210216/7019

CONTINUATION OF REPORT

ES9000G caused the damage to SMT9177E.

I have attempted to contact Secure Parking Singapore Pte Ltd to obtain CCTV from Goodwill Court's private parking lot and was directed to file a police report. The accident reporting centre advised the same in order to obtain the CCTV footage in addition to the front and rear camera views recorded automatically by the in-vehicle sensors of SMT9177E.





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

Informant is not able to provide sketch

Sketch Plan

4 of 4 Report No. T/20210216/7019

CONTINUATION OF REPORT

Signature Of Officer Recording The Report:	Signature Of Informant:
Not applicable	The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter:	Date/Time:
Not applicable	16/02/2021 14:17
Officer In Charge Of Case:	Classification Of Case:
Officer In Charge Of Case: TP / TPIB /	Glassification of case.
GOH GEOK LYE	

NP168

Authentication Stamp