NA2 | REF: CS3/GRB21002215/Nvf3 | VR01

III

PAPER SURVEY

ASSIGNMENT

Date:

Estimated Cost:

WS / YR RES / OD RES / EVA / INV / MV

Insured Vehicle No.:

Vehicle Details:

Excess:

Comments:

N/S O/S

Time of Inspection:

43K

Chassis unit? Yes or No

Chassis unit? Yes or No

5 days Rest: Yes or No

Vehicle Value: Yes or No

24 HRS

Vehicle W/Out

Parts Delivered

Veh No: SCW 8880S Yr Regn: 2 JUN 2008

Type: M.Car / M.Cycle / BUS / Van / Lorry / Taxi / Prime Mover / Trailer or

Model: HONDA STREAM 1.8L A cc 1,799

Colour: BLUE A/C: Insured / Std / N/A

Sp Reading: 161,606 T/Belt: Insured / Std / N/A

Engine:

Chsi: JHMRN68408S203633

Gen. Cond. Good / Fair / Poor / Burnt

Steering: Jammed / Locked / Burnt or

Brake: Jammed / Locked / Burnt or

Wheels: N/A / Sports / STD / N/A or

Tyre Size: F: 205/65 R15

R: 11

BS / DUN / EXHOVA / GY / FS / LZA / MC / OTHSU / P.R / SUN / TOYO / YOKO or

Brand: Brand:

F/Bal: 5 mm Rad: 4

L/Bal: 5 mm L/Bal: 4

DOA: 4/2/2021 DOS: 17/2/2021

Survey Issued at: MOTOWERKS CONCEPT

Det. of Damages: Fr / Rear / O/S / N/S / U/C / Rollup or

Trip / U/C / Chassis frame / Body Structure / Radiator or

III L/S

Action / Instruction

COE Rebate $34,016.00

Repair Limit $8K

Prelim Report

Fin. Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Inspection:

Add Fee: Site Insp $

Design/Eng $

Technical Inv $

Miscellaneous $

19/2/21-Typist

PRS