NA2 | REF: | III | VR01

PAPER SURVEY

ASSIGNMENT

Date:

Estimated Cost:

WS / YR RES / OD RES / EVA / INV / MV

Insured Vehicle No.:

Vehicle Details:

Excess:

Comments:

N/S O/S

Vehicle Inspected at the time of Inspection

43K

Chassis unit? Yes or No

Chassis unit? Yes or No

5 days Road Yes or No

Vehicle Yes or No

24 HRS

Vehicle In / Out

Parts Delivered

Veh No: SCW 8880S Yr Regn: 2 JUN 2008

Type: M.Car / M.Cycle / BUS / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Model: HONDA STREAM 1.8L A cc 1,799

Colour: BLUE A/C: Insured / Std / N/A

Sp Reading: 161,606 T/Belt: Insured / Std / N/A

Engine:

Chas: JHMRN68408S203633

Gen. Cond. Good / Fair / Poor / Burnt

Steering: Horder / Jammed / Locked / Burnt or

Brake: Horder / Jammed / Locked / Burnt or

Wheels: Alloy / STD / Wire or

Tyre Size: F: 205/65 R15

R: 11

BS / DUN / EXHOVA / GY / FS / LZA / MC / OHTSU / P.R / SUN / TOYO / YOKO or

Dent		Dent	
F/Bal:	5 mm	R/Bal:	4
L/Bal:	5 mm	L/Bal:	4
DOA:	4/2/2021	DOS:	17/2/2021

Survey Issued at: MOTOWERKS CONCEPT

Det. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

Trip / U/C / Chassis frame / Body Structure / Radiator / Core or

III L/S

Action / Instruction

COE Rebate $34,016.00

Repair Limit $8K

Prelim Report

Fin. Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Add Fee: Site Insp $

Design/Eng $

Tech Inv $

Variance $