

ASS. REC. BY:

REF: CS/CTI21002224/R1vf3

Special Instruction:

Surveyor: RASULASSIGNMENT (Office)From (Person): ADELINE CHNG PEI WENof CTIDate/Time: 16 Feb 2021 16:36

Estimated Cost: _____

Bill to: _____

OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: _____

SLP 9080H

Insured: _____

PC 8938L

at Workshop m/s _____

Xinya Auto Services Pte Ltd

Tel: _____

6270 3481of Blk 1002, #01-75, Bukit Merah Lane 3, 159719 Bukit Merah

Policy No: _____

Claim No: _____

SNM21D200868

Sum Insured: _____

Excess: _____

Make of Veh: _____

D.O.A. 11/02/2021

(Client's Record)

"WP"

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 16-02-2021 5.32P.MPerson Contacted: XIN YAVehicle IN ☒ OUT

Date/Time	Action/Instruction (☒) Estimate
	SLP 9080H- NBA/INC21002108/Y DOA:11/02/2021
	PC 8938L- NBA/INC21002108/Y DOA:11/02/2021