

ASS. REC. BY:

REF: CS3/AIG21002226/Bvf3

Special Instruction:

Surveyor: LIM

ASSIGNMENT (Office)

From (Person): Divyashni Subramaniam of AIG Date/Time: 16 February 2021 6:38 PM

Estimated Cost: Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMW 5940D Insured: GBH 7538D

at Workshop m/s Lian Heng Painter Company Tel: 64535779

of 160 Sin Ming Drive #06-10 Sin Ming Auto City

Policy No: Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 06/02/2021
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 17-02-21 11.08A.M

Person Contacted: LIAN HENG

Vehicle ☒ IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SMW 5940D - X
	GBH 7538D - CS3/AIG19016244/Acd3e2 DOA :06/09/2019