

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Trans Cab

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: R27,897.1

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: S11C 5982 Y Yr Regn: 12, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Peugeot Latitude c.c. 1995

Colour M. White / Red A/C: Insured / Std / NI / NA

Sp. Reading 848366 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VIFI ABLISAUC 280993

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or Spilun

Front

Rear

R/Bal. 9 mm

R/Bal. 8 mm

L/Bal. 9 mm

L/Bal. 8 mm

D.O.A. 11/2/21

D.O.I. 16/2/2021

Survey held at _____

Des. of Damages: Frt Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 May have BT

Date/Time, File Pass to?

: Prell. Report

Days Of Repair: _____

1) Date/Time, File Return to?

: Final Report

Resurvey No. of Trip: _____

Survey Fee:

2) _____

Add Fee: : Site Insp (\$)

Transportation:

: Interview (\$)

\$ - RS. SI

: Tech Invs (\$)

Fees

: Weekend (\$)

Others

Report Format :

Lump Sum / I.B.I: (\$)

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5982Y

AAD2102-059

Not Authorised
L/Syng B

Vehicle No.:
Chassis No.:
Vehicle Make: **16 FEB 2021**
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

SHC5982Y
VF1ABL15AUC280993
RENAULT
LATITUDE
11/02/2021
CHINA
18/12/2014

	PART		LIST	
1	1 REAR BOOT	\$	R 1,677.20	✓
2	1 BOOT FINISHER	\$	R 344.70	X
3	1 BOOT STRUT LH	\$	S 145.10	X
4	1 BOOT STRUT RH	\$	S 145.10	X
5	1 BOOT WEATHERSTRIP	\$	W 178.20	50W
6	1 BOOT HINGE LH	\$	R 254.20	X
7	1 BOOT HINGE RH	\$	R 254.20	X
8	1 BOOT BADGE 'RENAULT'	\$	R 82.40	✓
9	1 BOOT BADGE	\$	R 95.80	✓
10	1 BOOT LOCK	\$	R 246.60	X
11	1 BOOT REFLECTOR LAMP LH	\$	R 277.70	✓
12	1 BOOT REFLECTOR LAMP RH	\$	R 277.70	✓
13	1 BUMPER COVER REAR	\$	R 561.70	✓
14	1 BUMPER LOWER REAR	\$	R 411.90	✓
15	1 BUMPER REFLECTOR LH	\$	C 16.60	✓
16	1 BUMPER REFLECTOR RH	\$	S 16.60	X
17	1 BUMPER BRACKET CTR REAR	\$	D 98.10	✓
18	1 BUMPER BRACKET SIDE RH REAR	\$	S 82.10	X
19	1 BUMPER RETAINER RH REAR	\$	S 59.80	X
20	1 BUMPER BRACKET SIDE LH REAR	\$	S 80.80	X
21	1 BUMPER RETAINER LH REAR	\$	S 54.20	X
22	1 BUMPER BEAM REAR	\$	R 547.80	✓
23	1 BUMPER BEAM BRACKET LH REAR	\$	R 114.50	✓
24	1 BUMPER BEAM BRACKET RH REAR	\$	R 114.50	✓
25	1 OUTER PANEL REAR (End Panel)	\$	R 745.80	✓
26	1 OUTER PANEL REAR (End Panel)TRIM	\$	R 404.56	✓
27	1 FENDER PANEL REAR LH	\$	R 1,933.20	X

Trans-cab Auto Services Pte Ltd

AAD2102-059

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5982Y

28	1 WHEELARCH REAR LH	\$	Sm 275.40	X
29	1 TAILLAMP LH	\$	mg cm 401.40	✓
30	1 TAILLAMP RH	\$	4 4 401.40	✓
		\$	10,299.26	
		10% \$	1,029.93	
		\$	9,269.33	

Special Nett

1	1SET PARKING AID	\$	Nullshot 700.00	400.00
2	1SET FENDER CLIP	\$	na 65.00	X
3	1SET FENDER LINER CLIP	\$	na 60.00	X
4	1SET REAR BUMPER CLIP	\$	na 66.00	✓
5	1SET BUMPER BRACKET CTR CLIP	\$	na 33.00	X
6	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na 10.00	X
7	1SET BUMPER RETAINER RH CLIP RR	\$	na 20.00	X
8	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na 10.00	X
9	1SET BUMPER RETAINER CLIP LH RR	\$	na 20.00	X
10	1SET BUMPER LOWER REAR CLIP	\$	na 66.00	✓
11	1 EXHAUST MOUNTING REAR	\$	Sm 17.82	} X
12	1 BUMPER CLIP FRT	\$	Sm 85.00	
13	1 BUMPER RETAINER CLIP FRT	\$	Sm 70.00	
14	1 BUMPER GRILLE LOWER CLIP	\$	na 70.00	
15	1 LICENSE PLATE WITH HOLDER FRT	\$	Sm 120.00	
16	2 WINDSCREEN SEALANT	\$	na 150.00	
17	1 WINDSCREEN MOULDING	\$	na 200.00	
18	1 WINDSCREEN INNER SPONGE SEAL	\$	na 130.00	
	TOTAL	\$	1,412.82	
	TOTAL PARTS	\$	10,682.15	

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	na 300.00	X
Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	8801

Trans-cab Auto Services Pte Ltd

AAD2102-059

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5982Y

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	<i>Foot</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>bol</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>bol</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	<i>bol</i>
To repair and realign rear exhaust pipe.	\$	<i>na</i> 170.00	<i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>na</i> 170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	<i>bol</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>na</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>bol</i>

TOTAL \$ 7,880.00

Over All Total \$ 27,831.49

(LUMP SUM)

Repair Days

20 DAYS

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 12/02/2021 02:04 (SGT)
Date of Accident 11/02/2021 14:50 (SGT)
Exact Location of Accident Sengkang, Singapore
Additional Location Information SENGKANG E ROAD TOWARDS TPE (CHANGI)
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHC5982Y

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner TRANS-CAB SERVICES PTE LTD
Company Reg No 2XXXXX878K
Email Address claims@transcab.com.sg
Mobile Phone No (Phone) +65-62866666
Alternative Phone No (Office) +65-62866666

VEHICLE PARTICULARS

Manufacturer Renault
Model Latitude
Variant -
Exact purpose for which vehicle was being used at time of accident Private hire
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Taxi

INSURANCE COMPANY

Name of Insurance Company Axa
Type of Coverage ThirdParty
Fleet Policy Yes
Policy Number VFX/P2413997
Cover Note Number -

DRIVER

Name of Driver NG THIAM MENG
NRIC No SXXXX601C
Date Of Birth 24/09/1968
Occupation Outdoor

Date Of Driving Pass 24/09/1999
 Driving experience 21 YEARS AND 5 MONTHS
 Gender Male
 Mobile Number (Phone) +65-81884040
 Alt. Phone Number -
 Email Address claims@transcab.com.sg
 Address HDB Ping An Gardens, 59 Chai Chee Road
 Address complement #02-866
 Postcode 460059
 Is the driver the policyholder? No
 If No, Relationship of the Driver with the Insured Hirer
 Does Driver Own Other Vehicles? No
 Vehicle Registration Number of Other Vehicle Owned by Driver -
 Insurance Company of Other Vehicle Owned by Driver -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Chain Collision
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 3
 Was anybody injured in the Accident? No
 Was any injured conveyed to hospital by ambulance? -
 Was any other material or property damaged? Yes
 Number of Passengers (Including Driver) 4
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

PASSENGER 1

Name PASSENGER 1 - MALAY
 Gender Female

PASSENGER 2

Name PASSENGER 2 - MALAY
 Gender Male

PASSENGER 3

Name PASSENGER 3 - MALAY
 Gender Male

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

I WAS DRIVING ALONG SENGKANG E ROAD TOWARDS TPE . AFTER TURNED RIGHT INTO SLIP ROAD , I SLOWED DOWN MY VEHICLE AS THE TRAFFIC HEAVY . SUDDENLY VEHICLE B COLLIDED ONTO REAR OF MY VEHICLE . TOTAL 3 VEHICLES INVOLVED AND I WILL GO SEE A DOCTOR LATER .

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? No
 Was there any audio recorded? No

ACCIDENT STATEMENT (2000 characters)

I WAS DRIVING ALONG SENGKANG E ROAD TOWARDS TPE . AFTER TURNED RIGHT INTO SLIP ROAD , I SLOWED DOWN MY VEHICLE AS THE TRAFFIC HEAVY . SUDDENLY VEHICLE B COLLIDED ONTO REAR OF MY VEHICLE . TOTAL 3 VEHICLES INVOLVED AND I WILL GO SEE A DOCTOR LATER .

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
WONG JUN KEAT

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

11 February 2021 at 7:07 PM

Date/Time:

11 February 2021 at 7:07 PM