

FCI/210022561K+

Кельотх

ASSIGNMENT

Veh No: TSG 5783 Yr Regn: 08, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Yamaha 135 c.c. 13F

Colour White / Grey / Black A/C: Insured / Std / NI / NA

Sp. Reading 84802 T/Radio: Insured / Std / NI / NA

Eng/No: _____
C/No: PMYUGO420FF0094/69

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD A/Rlm or

Tyre Size: F: *mic* *70/90 R17*

N/S	O/S

R: Pi- 20/90R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO/YOKO or

Front Rear

VBal. 6 mm R/Bal. 5 mm

UBal.	mm	UBal.	mm
-------	----	-------	----

D.O.A. 27/10/20 D.O.I. 9/3/22

Survey held at _____

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

km & o/s bod.

Date / Time	Action / Instruction
/	
	confirm lump sum \$1100, 4 days red:15216.75;93%

☐ : Prel. Report
☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip:

Survey Fee:

2

Add Fee: ☐ : Site Insp (\$
☐ : Interview (\$
☐ Tech Invs (\$
☐ Weekend (\$

Transportation
S + RS. SI
F. 1000
Others

Report Format :

Lump Sum / I.B.I: (S

TOTAL

390