

FCI/210022561K+

Кельотх

Veh No: TSG 5763 Yr Regn: 08, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha 135 c.c. 135

Colour White / Grey / Black A/C: Insured / Std / NI / NA

Sp. Reading 86802 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: PMYUGO420/H0094/69

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / ~~STD~~ A/Rlm or

Tyre Size: F: *mic 70/90 R17*

R: *Pir* 80/80R17

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO/YOKO or

Front

R/Bal. 6 mm

R/Ba! 5 mm

L/Bal. mm

UBal. 1711

D.O.A. 27/10/20

D.O.I. 97372021

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

es. of Damages : Frt / Rear / O/S / N/A
Rm & o/s both

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
/	
	confirm lump sum \$1100, 4 days red:15216.75;93%

16316.75

☐: Prell. Report

☐: Final Report

Days Of Repair: 4

Resurvey No. of Trip:

Survey Fee:

Transportation: $S = RS, SI$

Add Fee: : Site Insp (\$

□: Interview (\$

☐ Tech Invs (\$

☐ Weekend IS

Report Format :

Lump Sum / I.B.I: (S

TOTAL



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 576722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopte ltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S: First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

ATTN: Motor Claim Department
Your Ref No: -
Claim Type: Third Party
Accident Date: 27/10/2020
TP Veh Reg No: SHB4759M

Estimate No: ES2100018
Date: 19 Feb 2021
Policy No:
Veh Reg No: JSG5763
Make/Model: YAMAHA 135LC
Chassis No: PMYUG0420H0094169
Engine No: G399E593269
Reg. Date:

Estimate Repair Cost to Vehicle No :JSG5763

Description	U/Price	Quantity	List Price S\$	Amount S\$
Net Price				
1 FRONT NUMBER PLATE	50.00	1 PC	50.00 X	
2 FRONT WHEEL RIM	580.15	1 PC	580.15	630.15
			630.15	
Spare Parts				
3 BATTERY	100.00	1 PC	100.00 X	
4 BRAKE CALIPER	380.15	1 PC	380.15 X	
5 BRAKE LEVER	88.20	1 PC	88.20 X	
6 BRAKE OIL	40.00	1 PC	40.00 X	
7 BRAKE PEDAL - RH	178.20	1 PC	178.20 ✓	
8 ENGINE BLOCK COVER - LH (BLACK)	225.00	1 PC	225.00 X	
9 ENGINE BLOCK COVER - RH (BLACK)	225.00	1 PC	225.00 X	
10 ENGINE BLOCK LOWER COVER	342.00	1 PC	342.00 ?	
11 ENGINE COVER	385.15	1 PC	385.15 X	
12 EXHAUST - LH	1,260.00	1 PC	1,260.00 X	
13 EXHAUST COVER	285.15	1 PC	285.15 ✓	
14 FRONT BRAKE ROTOR - RH	380.00	1 PC	380.00 ✓	
15 FRONT FENDER	195.15	1 PC	195.15 ✓	
16 FRONT FORK - LH	890.50	1 PC	890.50 ✓	
17 FRONT FORK - RH	890.50	1 PC	890.50 ✓	
18 FRONT FORK BEARING	85.15	1 PC	85.15 ✓	
19 FRONT FORK COVER - LH	349.20	1 PC	349.20 X	
20 FRONT FORK COVER - RH	349.20	1 PC	349.20 ✓	
21 FRONT FORK TUBE - LH	520.15	1 PC	520.15 ?	
22 FRONT FORK TUBE - RH	520.15	1 PC	520.15 ?	
23 FRONT HANDLE BAR	320.00	1 PC	320.00 ?	
24 FRONT HANDLE BAR BALANCER - LH	80.00	1 PC	80.00 X	
25 FRONT HANDLE BAR BALANCER - RH	80.00	1 PC	80.00 ✓	
26 FRONT HEAD LAMP COVER	185.15	1 PC	185.15 X	
27 FRONT LEG REST	320.15	1 PC	320.15 ✓	
28 FRONT LOWER FORK BEARING (LOWER)	85.15	1 PC	85.15 ✓	
29 FRONT LOWER FORK BEARING (TOP)	85.15	1 PC	85.15 ✓	
30 FRONT LOWER FORK BRACKET	285.00	1 PC	285.00 ✓	
31 FRONT SIDE COWLING - CENTRE	235.05	1 PC	235.05 ✓	
32 FRONT SIDE COWLING - LH	295.15	1 PC	295.15 ✓	
33 FRONT SIDE COWLING - RH	295.15	1 PC	295.15 ✓	
34 FRONT SIDE COWLING INNER GARNISH - RH	180.45	1 PC	180.45 ✓	
35 FRONT SIDE COWLING INNER GARNISH - LH	180.45	1 PC	180.45 X	



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteLtd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S: First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

ATTN: Motor Claim Department
Your Ref No: -
Claim Type: Third Party
Accident Date: 27/10/2020
TP Veh Reg No: SHB4759M

Estimate No: ES2100018
Date: 19 Feb 2021
Policy No:
Veh Reg No: JSG5763
Make/Model: YAMAHA 135LC
Chassis No: PMYUG0420H0094169
Engine No: G399E593269
Reg. Date:

Estimate Repair Cost to Vehicle No :JSG5763

Description	U/Price	Quantity	List Price	Amount
			SS	SS
36 FRONT SIDE COWLING STICKER - CENTRE	65.20	1 PC	65.20	✓
37 FRONT SIDE COWLING STICKER - LH	72.15	1 PC	72.15	✓
38 FRONT SIDE COWLING STICKER - RH	72.15	1 PC	72.15	✓
39 FRONT SIDE STAND FOOT ENLARGER - LH	115.20	1 PC	115.20	X
40 FRONT SIDE STAND FOOT ENLARGER - RH	115.20	1 PC	115.20	?
41 FRONT SIGNAL LAMP - LH	95.00	1 PC	95.00	X
42 FRONT SIGNAL LAMP - RH	95.00	1 PC	95.00	✓
43 FRONT TOP FORK BEARING (TOP)	85.15	1 PC	85.15	?
44 GEAR PEDAL	90.00	1 PC	90.00	X
45 HANDLE GRIP - LH	40.00	1 PC	40.00	X
46 HANDLE GRIP - RH	40.00	1 PC	40.00	✓
47 HEAD LAMP	890.15	1 PC	890.15	X
48 RADIATOR	380.00	1 PC	380.00	?
49 REAR BOX	420.15	1 PC	420.15	✓
50 REAR LEG REST BRACKET - LH	280.15	1 PC	280.15	X
51 REAR SIDE COWLING - LH	220.15	1 PC	220.15	✓
52 REAR SIGNAL LAMP - LH	95.15	1 PC	95.15	✓
53 WING MIRROR - LH	90.05	1 PC	90.05	X
54 WING MIRROR - RH	90.05	1 PC	90.05	✓
			13,666.60	13,666.60
Labour				
55 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	800.00	1 JOB	800.00	1501
56 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	700.00	1 JOB	700.00	X
57 TO ALIGN MAIN BODY FRAME.	400.00	1 JOB	400.00	1801
58 TO TOW VEHICLE TO WORKSHOP.	120.00	1 JOB	120.00	301
			2,020.00	2,020.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SINGAPORE POLICE FORCE



T/20201225/2028

1 of 3

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

Report No. T/20201225/2028

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 25/12/2020 11:25	Vide Report No.:	Station Diary No.: 46
--	------------------	--------------------------

Name of Informant: MOGAN KUMAR A/L NATHEN		Address: 414 ANG MO KIO AVE 10 #02-917 APT BLK 417 BUKIT MERAH VIEW #10-175 SINGAPORE 451417-560414	
ID Type / ID No.: FIN NO / F1019966L		Contact No.: Home/Office: Mobile: 98648326	
Nationality: MALAYSIAN		Email:	
Sex: Male	Age: 60	Date of Birth: 03/05/1960	Type of Informant: Rider
Race: Indian		Language: English	Institution / School Name:
Occupation: Bus driver		Driving Licence Information: Class: 2B,3,4 Date of Expiry: 27/11/2023	

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 27/10/2020 21:15	Type of Location: T-Junction
Location: ALEXANDRA ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Vehicle No.	Type	Make	Model	Color	Condition	Assessment
JSG5763	Motorcycle					0
SHB4759M	Taxi					0

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



SINGAPORE POLICE FORCE



T/20201225/2028

2 of 3

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

Report No. T/20201225/2028

CONTINUATION OF REPORT

Name	MOGAN KUMAR A/L NATHEN	ID No.	F1019966L
Related Vehicle	JSG5763 (Motorcycle)	Contact No.	98648326
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3,4 Date of Expiry: NIL
Date Treatment	27/10/2020	Date Discharge	24/12/2020
No. of Days granted Medical Leave	30	Degree of Injury	NIL

Brief Details.

On 27/10/20 at about 2115hrs I was riding my motorcycle (JSG5763) along Alexandra Road towards City on the extreme left lane (3 lane road). While I was at the entrance of Alexandra Hospital entrance, at the yellow box, on the move when a Comfort Taxi (SHB4759M) made a sudden right turn from the opposite direction and collided onto the left side of my motorcycle. I was thrown off my motorcycle and landed on the road. I was still conscious at that point of time.

The taxi driver then stopped his taxi and came down to check on me. Ambulance was called in and I was conveyed to NUH for immediate treatment. I was warded there for about 3 weeks before they transferred me to Jurong Community Hospital for rehabilitation. I suffered fractures on both my foot, my right knee and my left shoulder.

I was given 30 days of medical leave after I was discharged from hospital. As I was warded for a long period I could not make a traffic accident report earlier. I also received 63 days of hospitalization

leave from Ang Mo Kio South NPC
81 Ang Mo Kio Ave 3
S'pore 569929
Tel: 1800 - 451 9999

MOTORCYCLE SCHEDULE / JADUAL MOTOSIKAL

motorcycle365 Comprehensive Plus

STAMP DUTY PAID
 LW-PW-8011(EJMT)
 REV: 8
 RTO Code: 08
 MOTOR CYCLE
 MYJ

The Insured / Pemegang Polisi MOGAN KUMAR A/L NATHEN			Policy No. / No. Polisi JVD9392587		70-M1	
NO 42 JALAN PULAI 41 TAMAN PULAI UTAMA 81300 JOHOR BAHRU			Account No. / No. Akaun N34800-00			
Occupation / Pekerjaan GENERAL WORKER			Bus. Regn. No / No Pendaftaran Perniagaan		Premium / Premium All Rider / Semua Penunggang	
I.C. No. / No. Kad Pengenalan 600503085763					RM 199.87	
Hire Purchase Owner / Pemilik Sewa Beli					RM 99.93	
Make & Type of Body / Buatn & Jenis Badan YAMAHA 135LC / MOTORCYCLE					NCD / Diskaun Tanpa Tuntutan 25.00%	
					RM 74.95	
					Wet / Berkualkuasa dari 06-08-2020	
					RM 224.85	
					Gross Premium / Premium Kasar	
					RM 224.85	
					Service Tax / Cukai Perkhidmatan 6%	
					RM 13.49	
					Stamp Duty / Duti Setem	
					RM 10.00	
Registration No. / No. Pendaftaran	Excess / Lebihan	Regn. Card No. / No. Kad Pendaftaran				
JSG5763	100.00					
Carrying or Seating Capacity Incl. Driver / Muatan Tempat Duduk Termasuk Pemandu	Tonnage / C.C. / Watt Tan / Keupayaan Enjin	Sum Insured / Jumlah Dilnsuranskan (RM)				
2	134.00 CC	5,300.00				
	Year of Manufacture / Tahun Diperbuat					
	2017					
Engine/Motor No. / No. Enjin/Motor	Chassis No. / No. Casis		Trailer / Troler			
G399E593269	PMYUG0420H0094169					
Only The Extensions, Endorsement And / Or Warranties Indicated Below Apply To This Policy. / Hanya Lanjutan, Endorsemen dan / atau Warranti sepertimana yang dinyatakan di bawah ini boleh diguna pakai dalam polisi ini.						
			Total Due / Jumlah Berbayar		RM 248.34	
			Total Due (OTC) / Jumlah Berbayar Di Kaunter		RM 248.35	

Subject to IMPORTANT NOTICE: Your duty as the Owner of the vehicle as attached.

Named Driver / Pemandu Yang Dinamakan

ALL RIDERS

Geographical Area : Malaysia, Republic of Singapore and Negara Brunei Darussalam. / Kawasan Geografi : Malaysia, Republik Singapura dan
Negara Brunei Darussalam.

Limitations as to Use / Authorised Driver : As described in the Certificate of Insurance. / Had Penggunaan / Pemandu Yang Diberi Kuasa : Seperti
yang tercatat dalam Sijil Insurans.

Replacing Cover Note No. /

Gentian No. Nota

Perlindungan

Renewal of Policy No. /

Pembaharuan No. Polisi

Date of Proposal or

Declaration /

Tarikh Cadangan atau

Pengisytiharan

28-07-2020

Issued By / Dikeluarkan Oleh :

NUR SEHA BINTI ESSA

ALAF MUTIARA SUPPLY & TRADING

NO 328, JLN KEMPAS 7

BANDAR PUTRA KULAI

81000 KULAI

JOHORE

Tel : 0107111734

Fax :

For / untuk

AmGeneral Insurance Berhad

AmGeneral Insurance

Authorised Signature /
Tandatangan Yang Diberi Kuasa

Date of Issue / Time

28-07-2020 12:44:25 PM

Tarikh Dikeluarkan / Waktu

408210280720C243

Note: / Note: No refund of premium for any cancellation of policy if premium is charged on minimum premium / Tiada bayaran balik premium bagi sebarang pembatalan polisi sekiranya
premium yang dikenakan adalah premium minima.

12JVG3PM600725-2