

Nivitha (LKK Auto)

From: K Krishna Partners <kkrishnaoffice@gmail.com>
Sent: Tuesday, 16 February 2021 3:51 PM
To: Motor Claims; CWS Motor Claims
Cc: yeeautopteltd@gmail.com
Subject: PRE-REPAIR INSPECTION OF VEHICLE SJS 5763 ACCIDENT ON 27.10.2020 INVOLVING JSR 5763 AND SHB 4759M ALONG KPE TOWARDS SIMS AVENUE

Follow Up Flag: CCPL PRI - D20004402MFSH
Flag Status: Flagged

Dear Sirs

We act for Mr Mogan Kumar A/L Nathen, the owner of motor vehicle no. **JSR 5763** which was involved in the above captioned accident.

We are instructed that the accident was caused by the negligence of the rider of motor vehicle no. **SHB 4759M**. Our search shows that you are the insurers of motor vehicle no. **SHB 4759M**.

We are requested to inform you that our client's vehicle is available for pre-repair inspection at the following address :-

M/S YEE AUTO PTE LTD
160 Sin Min Drive #02-17
Sin Ming Auto City
Singapore 575722
Tel; 64575768 Fax : 62528459

Please contact our client's workshop, **Mr Chan Kai Yee of M/s Yee Auto Pte Ltd** at his mobile no. **96874031** within **forty-eight (48) hours** from receipt of this fax to arrange for the inspection.

Regards

Farida on behalf of K. Krishna & Partners
Tel : 63233038
Fax : 63232120