

Date: 16.02.2021

Time: 16:24:12

Page: 1

REPAIR ESTIMATE

NTULC - CP/P)
LKK - Tanfich

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010070

ADDRESS : CITYCAB PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65551188

JOB NO : 305453936

REGN NO : SHD8809R

MILEAGE : 0000000000

MAKE : MERCEDES BENZ

MODEL : V-CLASS CDI 2.2L

DATE OF REGN : 06.08.2019

DATE/TIME IN : 15.02.2021 17:40

ACCIDENT DATE : 15.02.2021

JOB / PARTS DESCRIPTION

[illegible]

PART REQUISITION

0001 04-01-0204-0579-G	REAR BUMPER	1	1,372.00	20.00	1,097.60
------------------------	-------------	---	----------	-------	----------

0002 04-01-0103-1150-A	REAR BUMPER MAT	1	50.00	50.00
------------------------	-----------------	---	-------	-------

0003 22-01-0299-2011-A	TAILGATE MAXICAB LOGO	1	80.00	10.00	72.00
------------------------	-----------------------	---	-------	-------	-------

SUB-TOTAL : 1,219.60

JOB NATURE

~~XXX~~ PB PANEL BEATING-Tailgate Etc

500.00 400

0001 SP SPRAYPAINT CHARGE

600.00 500

SUB-TOTAL : 1,100.00

TOTAL : 2,319.60

\$2119.60

MVA NAME & SIGNATURE

DATA:

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE:

Tariffi 42495745
WP, 14/1/21 @ 450pm

205/65K16

2 boys #

2 days
P/P Resurg before print
Lampson (Hillman's son)

- The most important difference between the two is that the first is a primary and the second is a secondary source.
- The first is a primary source, meaning it is a source that is directly involved in the event.
- The second is a secondary source, meaning it is a source that is indirectly involved in the event.
- The first is a primary source, meaning it is a source that is directly involved in the event.
- The second is a secondary source, meaning it is a source that is indirectly involved in the event.

Abstract

Journal of Management Inquiry

600