SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 15/02/2021 12:58 (SGT) Date of Accident 14/02/2021 00:05 (SGT) Exact Location of Accident Yishun Ave 1, Singapore Additional Location Information Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Toyota

Vehicle Registration Number SHD2456P

INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner PRIME CAR RENTAL & TAXI SERVICES PTE LTD Company Reg No 199606293Z **Email Address** peivee@primeautoclaims.com Mobile Phone No (Phone) +65-68982000 Alternative Phone No (Office) +65-68610908

VEHICLE PARTICULARS

Manufacturer

Model Prius Variant Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Taxi

INSURANCE COMPANY

Name of Insurance Company India International Type of Coverage ThirdPartyFireTheft Fleet Policy Policy Number D20MFL0006372 Cover Note Number

DRIVER

Name of Driver G JEFRY KAPOOR NRIC No S1770020J Date Of Birth 25/01/1966 Occupation Outdoor

Date Of Driving Pass 22/07/2008 Driving experience 12 YEARS AND 7 MONTHS Gender Mobile Number (Phone) +65-88171893 Alt. Phone Number Email Address peiyee@primeautoclaims.com Address BLK 782E WOODLANDS CRESCENT #10-371 Address complement Postcode 735782 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Hirer Does Driver Own Other Vehicles? Nο Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Change/cross lane Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No PASSENGER 1 Name **PASSENGER** Gender Male **DETAILS OF POLICE ACTION** Was the accident reported to the police? Was notice of intended Prosecution given? Nο If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER ATTACHED STATEMENT ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No Was there any audio recorded? No **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number SLH7860D Vehicle Manufacturer Vehicle Model Vehicle Variant

Private car

Accident report SP0T212F0006

Vehicle Colour
Vehicle Category

Name of Driver
Contact Number

Address	 	_
Address complement	 	_
Postcode		_
Insurance Company Name	 	_
Nature Of Damage		_
Details of property damaged in accident	 	_
No. Of Passenger (Including Driver)		_

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre

Personnel

Sketch Plan



Describe Circumstances of the Accident

Refer attached statement	
1004157000000 000000000000000000000000000000	
	100.000
Declaration	
We declare the foregoing particulars are true in every respect.	
the seasons and totalknill barraging and are a season and a season.	

Driver's Signature (If driver is not the policyholder) / Date

& Time

Policyholder's Signature / Date & Time On 14.02.2020 @ 0005 hrs, I was driving my taxi SHD2456P with one male passenger along Yishun Avenue 1 on Lane 3. There was a car on Lane 3 blocking my way, thus I checked for traffic cleared then I proceed to filter to Lane 2 (Lane 2 can go straight or right turning.) When my taxi was travelled straight in Lane 2, out of sudden there was a car SLH7860D intended to travel straight instead of right turning, thus she changed lane from Lane 1 into my lane intention to go straight. As a result, SLH7860D left front portion collided into my taxi right front door and right front fender.

After the accident, we alighted from our vehicles to check on the damages. No one was injured in the accident.









