

12/02/2020

REF: CS3/SMO21000351/Uvd3-1

Special Instruction:

ASS. REC. BY:

Surveyor: MARCUS

ASSIGNMENT (Office)

17/02/2021

From (Person): GNOH PAU LOONG of SMO

Date/Time: 08/01/2021@10:57am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD  TP  RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKT 6901A

Insured: GBH 1401D

at Workshop m/s CARSMITH PRIVATE LIMITED

Tel: 9091 0000

of 13 KAKI BUKIT ROAD 4 #01-20

Policy No: \_\_\_\_\_

Claim No: CMTD2100076/GPL

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

Make of Veh:  
(Client's Record)

D.O.A. 07/01/2021

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 11.37AM@08/01/21

Person Contacted: ALEX

Vehicle IN/OUT

Date/Time	Action/Instruction ( X ) Estimate
	SKT 6901A-X
	GBH 1401D-X
13/1/21	Submit PRS, repair range \$2,000-\$3,000
22/2/21	Submit LS \$3250 (Red 3800.53%), 3 days