



SERVICE REQUESTS

MESSAGES

CLAIMS

Claim	S1M0337K
Reference	CS3/ASM21002315/Gvd3e2 
Loss Date	16 February 2021
Report Date	17 Feb 2021 3:58:00 PM
Request Date	18 February 2021
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pre-Repair Survey

Actions

Next Step Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident	SLM9011Z
Vehicle	
Registration #	
Make	TPVD Volkswagen
Model	JETTA 1.4 TSI

Service Address

’, ’

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

YU Dominic Yishan

English (SG) ▾

LKK AUTO CONSULTANTS PTE LTD (TP) ▾



SERVICE REQUESTS

MESSAGES

CLAIMS

Metrics

Notes

Document Type

Document SubType

[+ Upload Documents](#)

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
SLM9011Z TP GIA.pdf	Other	Other	do not reply	
ASM-LKKInvoice-AC2101194.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	26 February 2021
LKKPreRepairInspection.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	26 February 2021
IA \$5000 - \$6000 6 days.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 February 2021
LKKPhotosIn4.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	19 February 2021

English (SG) ▾

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

SUB-TYPE

AUTHOR

DATE
UPLOADED



SERVICE REQUESTS

MESSAGES

CLAIMS

Others

NIKAM Santosh Pandurang

17 February
2021

 [SLM9011Z TP GIA.pdf](#)

Reports & Statement

GIA Report

NIKAM Santosh Pandurang

17 February
2021

 [SH6136K INCIDENT ONLY.pdf](#)

Reports & Statement

GIA Report

CHOUGULE Kavita

17 February
2021