

ASS. REC. BY:

REF: CS3/ASM21002321/T1vf3

Special Instruction:

Surveyor: TAUFIKHASSIGNMENT (Office)From (Person): YU Dominic Yishan of AXA Date/Time: 18/2/2021 3:39 PM

Estimated Cost: _____ Bill to: _____

OD ☒ TP ☐ WS ☐ TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: GBK 3538P Insured: SHC 3265Yat Workshop m/s QAS Auto Pte Ltd Tel: 9857 9525of Blk 3018A Ubi Road 1 #01-23 Singapore 4087Policy No: _____ Claim No: S1M0359N

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 10-02-2021
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement: _____

Date/Time: 18-02-21 3.46P.M Person Contacted: GOH Vehicle IN ☒ OUT ☐

Date/Time	Action/Instruction (☒) Estimate
	GBK 3538P- ☒
	SHC 3265Y - NS/INC15010048/H1gbk3 DOA :16/06/2015
25/3/21	Send IA (PRS) via Smart Claim
25/3/21	Submit PRS, repair range \$1500-\$2500 (3 days)