

ASS. BY:

REF: CS | EG121002333 | Dtd<sup>3</sup>

## ASSIGNMENT

COR July 2025

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TPWS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured \_\_\_\_\_

Policy No. \_\_\_\_\_

Claim No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. of Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

7

days

Res.: Yes or No

Lump Sum: \_\_\_\_\_

10 20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: \_\_\_\_\_

SHA 1123Y

Yr Regn: \_\_\_\_\_

July, 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: \_\_\_\_\_

Toyota Prius

C.C. #

1798

Colour: \_\_\_\_\_

Blue

A/C: \_\_\_\_\_

Insured / Std / NI / NA

Sp. Reading: \_\_\_\_\_

231854

T/Radio: \_\_\_\_\_

Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

27R3056436

C/No: \_\_\_\_\_

STDKB3FU603561459

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: \_\_\_\_\_

F: \_\_\_\_\_

195/65 R15

R: \_\_\_\_\_

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal. \_\_\_\_\_

S'

mm

R/Bal. \_\_\_\_\_

S'

mm

L/Bal. \_\_\_\_\_

S'

mm

L/Bal. \_\_\_\_\_

S'

mm

D.O.A. \_\_\_\_\_

17/02/2021

D.O.I. \_\_\_\_\_

19/02/2021

Survey held at \_\_\_\_\_

Bijoyat Sin Ming

Des. of Damages: Fri / Rear / O/S / N/S / U/C / Rooftop or

Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time

Action / Instruction

Elgo XD 9918 M

Repair change most all parts with new parts. 1/1 at 10%

24/08/2021

Jman 2/5 16908/- with 7 yrs of exp  
CRed: 15,205.46 : 47%

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair: \_\_\_\_\_

7

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format: \_\_\_\_\_

Lump Sum / I.B.F. (\$

Lump Sum / I.B.F. (\$



# BIFROST AUTO PTE LTD

## REPAIR ESTIMATE

DATE: 18-Feb-21

INSURANCE: Ergo

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHA1123Y

DESCRIPTION	QTY	LIST PRICE	AMOUNT	
BONNET <i>Dent</i>	1	\$950.50	\$950.50	✓
INSULATOR, HOOD <i>Crack / broken</i>	1	\$398.10	\$398.10	✓
INSULATOR CLIPS 10 PCS <i>Rec</i>	1	\$36.80	\$36.80	✓
BONNET RUBBER <i>SR</i>	1	\$35.50	\$35.50	X
BONNET CABLE <i>HM</i>	1	\$83.20	\$83.20	X
BONNET HINGE (RH) <i>1st</i>	1	\$87.70	\$87.70	✓
BONNET HINGE (LH) <i>1st</i>	1	\$87.70	\$87.70	✓
BONNET LOCK <i>1st</i>	1	\$132.60	\$132.60	✓
CATCH, HOOD AUXILIARY HOOK <i>HM</i>	1	\$8.60	\$8.60	X
RADIATOR GRILLE <i>deformed</i>	1	\$438.00	\$438.00	✓
RADIATOR GRILLE EMBLEM <i>Rec</i>	1	\$88.00	\$88.00	✓
FRONT BUMPER COVER <i>Dent</i>	1	\$499.90	\$499.90	✓
FRONT BUMPER REINFORCEMENT <i>2 HM</i>	1	\$696.40	\$696.40	2 X
FRONT BUMPER REINFORCEMENT ABSORBER <i>HM</i>	1	\$115.70	\$115.70	X
FRONT BUMPER SPONGE <i>2 HM</i>	1	\$78.80	\$78.80	2 X
FRONT BUMPER LOWER GRILLE <i>HM</i>	1	\$166.90	\$166.90	X
FRONT BUMPER SIDE RETAINER <i>HM</i>	2	\$77.00	\$154.00	X
UNIT ASSY, HEADLAMP, RH (LED) <i>broken</i>	1	\$3,455.00	\$3,455.00	✓ 2637-60
UNIT ASSY, HEADLAMP, LH (LED) <i>broken</i>	1	\$3,455.00	\$3,455.00	✓ 2637-60
HEADLAMP ECU <i>HM</i>	2	\$682.60	\$1,365.20	X
HEAD LAMP PANEL (RH) <i>2 1st</i>	1	\$240.10	\$240.10	2 ✓
HEAD LAMP PANEL (LH) <i>2 1st</i>	1	\$240.10	\$240.10	2 ✓
TOP PANEL CENTRE <i>1st / Dent</i>	1	\$364.98	\$364.98	✓
TOP PANEL SIDE <i>2 2nd 1st</i>	1	\$145.90	\$145.90	2 ✓
RADIATOR ASSY <i>2 1st</i>	1	\$1,841.80	\$1,841.80	2 ✓
RADIATOR FAN GRILLE <i>HM</i>	1	\$632.40	\$632.40	X
GUIDE RADIATOR AIR NO.3 <i>HM</i>	1	\$299.70	\$299.70	X
COOLANT <i>HM</i>	1	\$45.00	\$45.00	X
DEFLECTOR, RADIATOR SIDE, RH <i>SR</i>	1	\$83.50	\$83.50	X
DEFLECTOR, RADIATOR SIDE, LH <i>SR</i>	1	\$83.50	\$83.50	X
STAY, RADIATOR SUPPORT, RH <i>HM</i>	1	\$65.70	\$65.70	X
STAY, RADIATOR SUPPORT, LH <i>HM</i>	1	\$65.70	\$65.70	X
RADIATOR FAN BLADE (RH) <i>HM</i>	1	\$233.10	\$233.10	X
RADIATOR FAN BLADE (LH) <i>HM</i>	1	\$233.10	\$233.10	X
RADIATOR FAN MOTOR (RH) <i>HM Dent</i>	1	\$543.70	\$543.70	✓
RADIATOR FAN MOTOR (LH) <i>HM Dent</i>	1	\$543.70	\$543.70	✓
RADIATOR FAN COWLING (LH/RH) <i>2 broken</i>	1 2	\$451.30	\$902.60	2 ✓
RESERVE TANK ASSY, RADIATOR W/O CAP <i>HM</i>	1	\$395.30	\$395.30	X
FENDER SUB-ASSY, FRONT RH <i>Dent</i>	1	\$945.30	\$945.30	✓
FENDER SUB-ASSY, FRONT LH <i>Dent</i>	1	\$945.30	\$945.30	✓
FRONT FENDER SHIELD <i>HM</i>	2	\$38.00	\$76.00	X



FRONT FENDER SHIELD CLIP <i>HL</i>	2	\$14.90	\$29.80
FRONT FENDER HYBRID EMBLEM, LH <i>HL</i>	1	\$86.50	\$86.50
FRONT FENDER HYBRID EMBLEM, RH <i>HL</i>	1	\$86.50	\$86.50
BRACKET, FRONT SIDE PANEL, RH <i>HL</i>	1	\$86.30	\$86.30
BRACKET, FRONT SIDE PANEL, LH <i>HL</i>	1	\$86.30	\$86.30
FRONT WINDSCREEN GLASS <i>Grade</i>	1	\$1,627.30	\$1,627.30
FRONT WINDSCREEN GLASS MOULDING <i>HL</i>	1	\$208.60	\$208.60
FRONT WINDSCREEN GLASS MOULDING LOWER <i>HL</i>	1	\$208.60	\$208.60
BLADE, FRONT WIPER, LH <i>HL</i>	1	\$56.70	\$56.70
WIPER TOP GARNISH <i>deluxe</i>	1	\$668.32	\$668.32
SUB TOTAL			\$24,405.00
LESS 20% <i>25%</i>			\$4,881.00
DISCOUNTED TOTAL			\$19,524.00
FRONT NO. PLATE <i>HL</i> SN	1	\$25.00	\$25.00
FRONT NO. PLATE TRIM COVER <i>HL</i> SN	1	\$30.00	\$30.00
FRONT NO. PLATE GARNISH <i>HL</i> SN	1	\$99.00	\$99.00
FRONT FENDER ADVERTISEMENT LOGO (LH/RH) <i>HL</i> SN	2	\$100.00	\$200.00
SUB TOTAL			\$354.00
Labour Charge			
Panel Beating	1	\$1,600.00	\$1,600.00
Spray Painting Charge	1	\$1,200.00	\$1,200.00
Wiring Charge	1	\$120.00	\$120.00
Tuff Kote	1	\$100.00	\$100.00
Towing Charge	1	\$80.00	\$80.00
Remove/Refix Radiator	1	\$90.00	\$90.00
Remove/Refix Aircon & Refill Gas	1	\$130.00	\$130.00
Remove/Refix Fuse Box	1	\$120.00	\$120.00
Remove/Refix Front Windscreen Glass	1	\$120.00	\$120.00
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00
TOTAL LABOUR			\$4,110.00
ESTIMATE TOTAL			\$23,988.00
will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

17142.50  
12866.87

200.00

1200/-  
800/-  
30/-  
40/-  
HL  
50/-  
80/-  
HL  
80/-  
150/-

2430.00

32105.76

19/02/2021 0915hr

NA Andru

2/3rd 7 days.

Yan

JKK Andu

15486.87

Supp 3337.51

18824.38

4/5 16,900/-

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# BIFROST AUTO PTE LTD

## Supplementary ESTIMATE

DATE: 22-Feb-21

INSURANCE: Ergo

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHA 1123Y (S)

DESCRIPTION	QTY	LIST PRICE	AMOUNT
TOP PANEL SIDE (LH) <i>st</i>	1	\$145.90	\$145.90
BRACE PANEL <i>st</i>	1	\$75.20	\$75.20
RADIATOR RETUN HOSE <i>st</i>	1	\$395.30	\$395.30
CLEANER ASSY, AIR <i>broken</i>	1	\$970.30	\$970.30
INTAKE AIR FLOW (AIR FLOW SENSOR) <i>en</i>	1	\$344.60	\$344.60
CONDENSER ASSY, W/RECEIVER <i>st   broken</i>	1	\$1,336.60	\$1,336.60
WIPER TOP GARNISH PANEL <i>st</i>	1	\$968.32	\$968.32
ENGINE TOP COVER <i>white</i>	1	\$474.63	\$474.63
BATTERY TERMINAL COVER <i>broken</i>	1	\$188.80	\$188.80
DASHBOARD TOP COVER <i>en</i>	1	\$4,863.95	\$4,863.95
FRONT WINDSCREEN GLASS MOULDING LH side <i>clack</i>	1	\$183.60	\$183.60
SUB TOTAL			\$9,947.20
LESS 20% <i>25%</i>			\$1,989.44
DISCOUNTED TOTAL			\$7,957.76
BATTERY <i>cut 50% depreciation</i> SN	1	\$220.00	\$220.00
		160.00	
SUB TOTAL			\$220.00
ESTIMATE TOTAL			\$8,177.76

✓  
✓  
X  
✓  
X  
✓  
✓  
✓  
✓  
X  
✓

4343.35

3257.51

80/-

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

*Yan*  
*2kk Auto*  
*[Signature]*

3337.51



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SHA1123Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	18 Feb 2021
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	2ZRS056436
Chassis No.:	JTDKB3FU603561459
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	19 Jul 2017
First Registration Date:	19 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jul 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jul 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$38,560.00
COE Rebate Amount:	\$21,288.00
Total Rebate Amount:	\$25,038.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 18 Feb 2021

OK

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	17/02/2021 16:55 (SGT)
Date of Accident	17/02/2021 12:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	SUNGEI TENGAH
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA1123Y
-----------------------------	----------

### INSURED/POLICYHOLDER

Is company?	Yes
Name of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Company Reg No	1XXXXXX21R
Email Address	fleetsafety@cdgtaxi.com.sg
Mobile Phone No	(Phone) +65-65508768
Alternative Phone No	(Office) +65-65508768

### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi

### INSURANCE COMPANY

Name of Insurance Company	Axa
Type of Coverage	ThirdPartyFireTheft
Fleet Policy	Yes
Policy Number	VFX/P2419138
Cover Note Number	-

### DRIVER

Name of Driver	ANG CHENG HO
NRIC No	SXXXX349G
Date Of Birth	09/01/1954
Occupation	Outdoor

Driving Pass  
experience  
Vehicle Number  
Phone Number  
Email Address  
Address  
Address complement  
Postcode  
Is the driver the policyholder?  
If No, Relationship of the Driver with the Insured  
Does Driver Own Other Vehicles?  
Vehicle Registration Number of Other Vehicle Owned by Driver  
Insurance Company of Other Vehicle Owned by Driver

13/08/1979  
41 YEARS AND 6 MONTHS  
Male  
(Phone) +65-96319189  
-  
fleetsafety@cdgtaxi.com.sg  
BLK 541 JURONG WEST AVE 1  
#04-1058  
640541  
No  
Other  
No  
-  
-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident  
Weather Conditions  
Road Surface  
Collision - Head to Rear  
Clear  
Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?  
Number of vehicles involved in the accident  
Was anybody injured in the Accident?  
Was any injured conveyed to hospital by ambulance?  
Was any other material or property damaged?  
Number of Passengers (Including Driver)  
Has the driver been approached by unknown person(s)  
soliciting/offering accident claims assistance?  
No  
2  
No  
-  
Yes  
1  
No  
No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?  
Was notice of intended Prosecution given?  
If yes, against whom?  
No  
No  
-

#### CIRCUMSTANCES OF ACCIDENT

PLS REFER TO ATTACHED  
Type of accident: 3P REVERSE

#### ATTACHMENT(S)

Are accident photos available for attachment?  
Was there any video captured by Car Camera?  
Was there any audio recorded?  
Yes  
Yes  
No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number  
Vehicle Manufacturer  
Vehicle Model  
Vehicle Variant  
Vehicle Colour  
Vehicle Category  
Name of Driver  
Contact Number  
Address  
Address complement  
XD9918M  
-  
-  
-  
-  
Commercial vehicle  
CHAN YIAN WAH  
(Phone) +65-93838823  
-  
-



Company Name  
Damage  
Property damaged in accident  
Passenger (Including Driver)

MODERATE  
REAR



## SKETCH PLAN

### IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


AFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 17.02.2021  
@ 15:00 hrs

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

A - SHA 1123Y  
B - XD 9918M



Along Sungei Tengah

**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

On 17.02.2021 at about 12:30 hours I was travelling along Sungei Tengah with

no passenger onboard .

While I was at a stationary position , suddenly veh B ( XD 9918M ) reverse and  
collided into my taxi A - Front Portion .

I have company video and photos at scene to support my claims .

Veh B ( XD 9918M ) - Mr Chan Yian Wah H/P : 9383 8823

**DECLARATION**

I/We declare the foregoing particulars are true in every respect.

**COMFORT TRANSPORTATION PTE LTD**  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 17.02.2021  
@ 15:00 hrs

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.: