



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 16/02/2021

User ID : BoonChewTay

### Section A - Accident Details

Registration Number	SMB1333T
Case Reference Number	BUS/02/21/1015
Registration Date	25/3/2013
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Vicknesh S/O Letchiman
Type of Accident	Side Swipe
Accident Date and Time	9/2/2021 3:55 PM
Accident Reported Date and Time	9/2/2021 8:45 AM
Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1333T - RIGHT CENTRE PORTION SGW8833G (TP) - INSURED WITH AIG
Prepared Date and Time	10/2/2021 5:34 PM
Chassis Number	WMAA22ZZ4D7001776
Mileage	
Work Shop	
Repair Completion Date and Time	

### Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$0.00
Total Spray Cost	\$1,296.00	\$0.00
Total Spare Part Cost	\$5,213.61	\$0.00
Total Other Cost	\$0.00	\$0.00
<b>TOTAL COST</b>	<b>\$8,099.61</b>	<b>\$0.00</b>
Lump Sum Total	\$8,100.00	\$0.00
Number of Repair Days	6.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	10/02/2021 5:43 PM	
Signature		<input checked="" type="checkbox"/>
Remarks		

### Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



## SMRT Accident Vehicle Repair Estimates

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 16/02/2021

User ID : BoonChewTay

### Section D - Details of Repair Estimates

Part 1 - Labour Works									
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable							
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,590.00	1060							
<b>Total Labour</b>	<b>\$1,590.00</b>								
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable							
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$1,296.00	1126.							
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,296.00</b>								
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable							
<b>Total Other Costs</b>									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
011477			LOCK, LEVER, LATCH WITH KEY FOR MAN A22	2.00	\$27.50	10.00	\$49.50	Replace	✓ CRU
010303	VE	4001B05-LAM141	LAMP, INDICATOR, SIDE: LED (MAN BUS)	1.00	\$186.10	10.00	\$167.49	Replace	✓ CRU
010330			WHEEL ARCH TRIM	1.00	\$124.20	10.00	\$111.78	Replace	✗ R
010062	Body	F01001-CW273	COVER-REAR TAIL LAMP, RH, FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	✗ R
009992	BODY RH	A01001-CW564	PANEL, SIDE: R11, FOR MAN A22 BUS	1.00	\$1,782.50	10.00	\$1,604.25	Replace	✗ R
009991	BODY RH	4000F06-ACCE4526	PANEL, SIDE: R10, FOR MAN A22 BUS	1.00	\$192.70	10.00	\$173.43	Replace	✗ R
009990	BODY RH	A01001-CW565	PANEL, SIDE: R9 WITH FRAME, FOR MAN A22 BUS	1.00	\$710.70	10.00	\$639.63	Replace	✗ R
009989	BODY RH	A01001-CW566	PANEL, SIDE: R8, FOR MAN A22 BUS	1.00	\$330.70	10.00	\$297.63	Replace	✗ R
009988	BODY RH	A01001-CW567	PANEL, SIDE: R7, FOR MAN A22 BUS	1.00	\$885.50	10.00	\$796.95	Replace	✗ R
009987	BODY RH	A01001-CW568	PANEL, SIDE: R6, FOR MAN A22 BUS	1.00	\$1,776.80	10.00	\$1,599.12	Replace	✗ R
			STICKER SMRT	1.00	\$200.00	0.00	\$200.00	Replace	✓ NCC
<b>Total</b>					<b>\$7,191.40</b>		<b>\$6,517.01</b>		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Repair day - 4 days

LIS

After paint photo

Sun Pn (24/02)

16/02/2021

TP without prejudice.

Page 2 of 2

Acknowledged by Repairer

Signature:

Date: