

ASS. REC. BY:

REF: CS/SMO21002357/Uvf3

Special Instruction:

Surveyor: MARCUS

ASSIGNMENT (Office)

From (Person): GRACE TEO of SMO Date/Time: 19/2/2021 8:01 AM

Estimated Cost: Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGS 8188G Insured: SLN 2617S

at Workshop m/s Xin Yun Auto Pte Ltd Tel: 9839155

of Blk 8 Kaki Bukit Avenue 4 #05-23 Premier @ Kaki Bukit

Policy No: Claim No: CMTD2100528/SYH

Sum Insured: Excess:

Make of Veh: D.O.A. 17 FEBRUARY 2021
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP"

H.O.D. Endorsement:

Date/Time: 19-02-21 10.58A.M Person Contacted: YI XIN Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (☒) Estimate
	SGS 8188G - CS3/AXA14020230/T1vj3d1-1 DOA :25/10/2014
	SLN 2617S - X