

ASS. REC. BY:

REF: CS3/CTI21002368/R1vf3

Special Instruction:

Surveyor: RASULASSIGNMENT (Office)From (Person): IRENE TAY HUI PING of CTI Date/Time: 19/2/2021 12:19 PM

Estimated Cost: _____ Bill to: _____

OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: YJ 8828C Insured: YN 768Zat Workshop m/s Yee Keong Motor Engineering Tel: 9780 8928of No 14 Penjuru RoadPolicy No: DMCVSN19352619000 Claim No: SNM20D202338

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 02-07-2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 19-02-21 1.03P.M Person Contacted: HIEW Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (☒) Estimate
	YJ 8828C- NA/MSG16020095/k4 DOA :25/07/2016
	YN 768Z- NA/CTI19020990/h4 DOA :26/11/2019
23/2/21	Submit PRS,repair range \$6,000-\$7,000 (9 days)