

NA2

REF


CTI

JUMARN

ASSIGNMENT

Date: _____
 Type: M.Cycle / Bus / Van / Lorry / ☒ Private / Other
 Track / Trailer or _____
 Make: HYUNDAI IYO
 Colour: BLUE
 Se Reading: 724,813
 Engine: _____
 Chassis: KMHLB41UMH096597
 Gen. Cond. Good / ☒ Fair / Poor / Bunk
 Steering: ☒ Harder / Jammed / Locked / Burnt or
 Brake: ☒ Harder / Jammed / Locked / Burnt or
 Motor: ☒ OK / Stalling / ☒ STD A/R / Other

Vehicle No. SHA 4202 H Yr Reg. 24 NOV 2016
 Type: M.Cycle / Bus / Van / Lorry / ☒ Private / Other
 Track / Trailer or _____
 Make: HYUNDAI IYO
 Colour: BLUE
 Se Reading: 724,813
 Engine: _____
 Chassis: KMHLB41UMH096597
 Gen. Cond. Good / ☒ Fair / Poor / Bunk
 Steering: ☒ Harder / Jammed / Locked / Burnt or
 Brake: ☒ Harder / Jammed / Locked / Burnt or
 Motor: ☒ OK / Stalling / ☒ STD A/R / Other
 Tyre Size: IF: 205/60 R16
 R: 11



Condition: _____
 Condition? Yes or No
 Condition? Yes or No
 Days: 3 days Res: Yes or No
 Valid: Yes or No

BS / COM / EX / NOVA / GY / PS / I / ZA / M / C / O / M / P / R / S / M /
 X WEYLAK or WESTLAKE
 Date: 17/02/2021
 Date: 17/02/2021
 Sunday: CDGE LOYANG

Vehicle: W/OUT

Det. of Damages: Frl / Rear / O/S / N/S / B/C / Rocking or
O/S REAR
 Yr. Old / Chassis / Frame / Body Structure / Studies / Other

Action / Instruction

CTI L/S

Print Report
 File Report

Days Of Repair: _____
 Restory No. of Trip: _____
 Sunday Fee: _____

Add Fee: ☐ Site Insp 15
☐ Interview 15
☐ Test / Insp 15
☐ Weekend 5

3-4-5
 1-2-3
 1-2-3
 1-2-3