


ASS. REC. BY: SteveREF: CC4/GR3 21902440/653

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD TR / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: \_\_\_\_\_  
at Workshop m/s \_\_\_\_\_  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record) \_\_\_\_\_  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SMS 85566 Yr Regn: 19/3/20  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: Mercedes-Benz E200 c.c. 1991  
Colour: Blue A/C: Insured / Std / NI / N  
Sp. Reading: 6524 T/Radio: Insured / Std / NI / N  
Eng/No: \_\_\_\_\_  
C/No: W00 213982A/4 9389  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brakes: In order / Jammed / Leaked / Burnt or  
Mod: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 245/45R18  
R: \_\_\_\_\_  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Pirelli  
Front Rear  
R/Bal. 4 mm R/Bal. 4 mm  
L/Bal. 4 mm U/Bal. 4 mm  
D.O.A. 11/2/21 D.O.I. 15/3/21  
Survey held at Cycle & Collage (Mercedes)  
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
F4 LH  
The UIC / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>MV-230K</u>

File/Time, File, Pass to?

☐ : Prel. Report  
☐ : Final Report

File/Time, File Return to?

Specimen:

Specimen / L.E.:

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Insp (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

\$ + RS. \$

Police

Others

TOTAL

[> Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	778J
<b>Vehicle Details</b>	
Vehicle No.:	SMS8556G
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Mar 2021
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E200 SEDAN AVG (R18 LED)
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	26492080024177
Chassis No.:	WDD2130802A749389
Maximum Power Output:	145.0 kW (194 bhp)
Open Market Value:	\$53,658.00
Original Registration Date:	19 Mar 2020
First Registration Date:	19 Mar 2020
Transfer Count:	0
Actual ARF Paid:	\$68,585.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Mar 2030
PARF Rebate Amount:	\$51,438.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	18 Mar 2030
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,889.00
COE Rebate Amount:	\$29,626.00
<b>Total Rebate Amount:</b>	<b>\$81,064.00</b>

The information contained herein is correct as at 15 Mar 2021

OK