

ASS. REC. BY:

REF: CS3/ASM21002457/Gvf3

Special Instruction:

Surveyor: GQ ASSIGNMENT (Office)

From (Person): CHAN KIAN CHUAN of AXA Date/Time: 22/2/2021 10:47 AM

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD /  WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMV 7820J Insured: SHA 4662M

at Workshop m/s GARAGE 13 Tel: 9853 5175

of 8 kaki bukit ave 4 #03-46 Premier @KB

Policy No: \_\_\_\_\_ Claim No: S1M033IY

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 06-02-2021  
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP" H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 22-02-21 5.22P.M Person Contacted: IRENE Vehicle IN  OUT

Date/Time	Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate
	SMV 7820J- <input checked="" type="checkbox"/>
	SHA 4662M- CC6/III19008900/Agb3q2 DOA : 20/05/2019
3/3/21	Send IA via Smart Claim (PRS)
3/3/21	Submit PRS, repair range \$2,000-\$3,000 (3 days)